




## JABAL HEMALAYA FOR INSPECTIONS



**Date of Inspection: 30-06-2025**

**Location:** RIYADH - KSA

**Type: DIESEL POWERED TELESCOPIC BOOM PLATFORM LIFT**

**Maker & Date of Manufacture:**

## JLG & 2018

Chassis No. / Serial No.

B300002437

Max. Horizontal Reach.

22.2m

**Note: Visual and Functional Test Were Satisfactory.**

Date of Next Examination

**29-12-2025**

At the time of inspection, the equipment was found satisfactory.

## IMAGES FOR MANLIFT



**THIS IS TO CERTIFY** that the Undersigned, a competent representative, did, attend to examine this equipment in accordance to the aforementioned standard to ascertain its safe working load and that the examination indicated that the said equipment has no indigenous injury or sighted deformation and the safe working load of the said equipment as either identified or test proof loaded is shown. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, implementation of our remarks & recommendations and qualified operators employed.

Surveyor's Name: **RIFAY**

Surveyor's Signature: \_\_\_\_\_

This certificate is granted subject to the condition that it is understood and agreed that nothing herein contained shall be deemed to relieve the undersigned of their obligation to their employees, agents and subcontractors. Under no circumstances whatsoever shall Jabal Hamaleya For Inspections nor their Engineer be held liable for any injury, death, damage, loss, or expense or for any negligent, negligent or implied, and Jabal Hamaleya For Inspections liability shall be limited to the acts or omissions of its employees, agents and subcontractors. Under no circumstances whatsoever shall Jabal Hamaleya For Inspections nor their Engineer be held liable for any injury, death, damage, loss, or expense or for any negligent, negligent or implied, or for any negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted standards and only those items actually inspected by Jabal Hamaleya For Inspections and which are covered only by this Certificate. Any person not bound to the contract pursuant to which this document is delivered may not assert claim against Jabal Hamaleya For Inspections for any liability arising out of errors or omissions which may be contained in said document and in connection with any activities for which it may provide. This certificate shall not be produced against me without the approval of Jabal Hamaleya For Inspections.

**Disclaimer: This certificate is issued subject to the observation made at the time of inspection. The company (Jabal Hemalaya) will not be held liable for any damage/losses associated to the equipment/materials.**

Address: Est. Jabal Hemalaya for Inspections, Saudi Arabia, Riyadh, Al Malaz Dist. Po. 12831  
CR No: 1010927177, Tel: 0112334900, Email: [info@jhinspection.com](mailto:info@jhinspection.com), [www.jhinspection.com](http://www.jhinspection.com)

# Annex to Certificate of Thorough Examination

Certificate No.: JHI-3149-25-C1

Date of Inspection: 30-06-2025

| No. | DESCRIPTION                      | CONDITION    | REMARKS |
|-----|----------------------------------|--------------|---------|
| 1.  | EQUIPMENT DOCUMENTS              | SATISFACTORY |         |
| 2.  | IDENTIFICATION ON CONTROL LEVERS | SATISFACTORY |         |
| 3.  | REFLECTIVE TAPE AND MARKINGS     | SATISFACTORY |         |
| 4.  | WORKING PLATFORM                 | SATISFACTORY |         |
| 5.  | ELECTRICAL SYSTEM                | SATISFACTORY |         |
| 6.  | HYDRAULIC SYSTEM                 | SATISFACTORY |         |
| 7.  | TYRES & WHEELS / TRACKS          | SATISFACTORY |         |
| 8.  | POWER UNIT CONTROL PANAL – UPPER | SATISFACTORY |         |
| 9.  | POWER UNIT CONTROL PANAL – LOWER | SATISFACTORY |         |
| 10. | OVER LOAD WARNING                | SATISFACTORY |         |
| 11. | EMERGENCY DESCENT                | SATISFACTORY |         |
| 12. | BRAKES                           | SATISFACTORY |         |
| 13. | BATTERY CONDITION                | SATISFACTORY |         |
| 14. | HORNS                            | SATISFACTORY |         |
| 15. | FIRE EXTINGUISHER                | SATISFACTORY |         |
| 16. | OVER ALL BODY CONDITION          | SATISFACTORY |         |
| 17. | GUARD RAILS                      | SATISFACTORY |         |
| 18. | MAINTENANCE RECORDS              | SATISFACTORY |         |

COMMENTS: At the time of inspection, the equipment was found satisfactory.

Surveyor's Name: RIFAY



Surveyor's Signature: