



LIFTING EQUIPMENT INSPECTION REPORT	Area DAMMON	Inspection Date DEC 09, 2023		Inspection Time 9:00	Previous Sticker No. 21-9606 Issued By BV
	Department / contractor SUDHAR	Equipment Number S40AJP-348	Equipment Location D/17/14RD	Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-23-0048
Manufacturer JLG	Model 1250AJP	Capacity 500LBS	Type MCWP	Equipment Serial Number 0300200688	Sticker Expiration Date JUNE 08, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

[illegible]