

BV No. 08647

LIFTING EQUIPMENT INSPECTION REPORT	Area Dormitory	Inspection Date MAR 23, 2021		Inspection Time —	Previous Sticker No. new
	Issued By				
Department / Contractor SUDITR	Equipment Number SJ14ESL-349	Equipment Location DMM Koro		Inspection Result ☒ Pass ☐ Fail	New Sticker No. 21-11450
Manufacturer JLG	Model R404S	Capacity 3500KG	Type manlift	Equipment Serial Number B200066878	Sticker Expiration Date SEP 22, 2021

Above Equipment Was inspected by **Bureau Veritas** in accordance with applicable Saudi Aramco GI's ASME and API standards. Deficiencies that require corrective action are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column

[illegible]