

## CERTIFICATE OF THOROUGH EXAMINATION AND / OR TEST OF LIFTING APPLIANCE OR ACCESSORY

|                                                                           |                                                                                                                                                             |                                  |                     |                                       |  |
|---------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|---------------------|---------------------------------------|--|
| Date of thorough examination: <b>31-07-2025</b>                           |                                                                                                                                                             | Date of issue: <b>31-07-2025</b> |                     | Report No.: <b>ESICO-LFT-R25-4971</b> |  |
| Name & Address of employer<br><b>SUDHIR EQUIPMENT RENTALS<br/>COMAPNY</b> |                                                                                                                                                             | Location<br><b>Riyadh</b>        |                     | Sticker No<br><b>6623</b>             |  |
|                                                                           |                                                                                                                                                             |                                  |                     | Standards<br><b>SASO ISO EN 280</b>   |  |
| Equipment Identification No                                               | Equipment Description                                                                                                                                       | Safe Working Load(s)             | Date of Manufacture | Manufacturer Name                     |  |
| <b>SJ14ESL-351 OR<br/>B200069493</b>                                      | <b>SCISSOR LIFT<br/>MODEL: R4045<br/>Max.platform height: 8.8m<br/>Max. working height:10.8m<br/>Max.number of occupatans: 2<br/>Max.wind speed: 28/mph</b> | <b>RATED LOAD<br/>249KG</b>      | <b>UNKNOWN</b>      | <b>JLG</b>                            |  |


|                                                                                                                                                                                        |     |   |    |                                     |                                                                                                                                                                              |     |                                     |    |                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|---|----|-------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-------------------------------------|----|-------------------------------------|
| Is this the first examination after installation or assembly at a new site or location?<br><br>If the answer to the above question is YES, has the equipment been installed correctly? | Yes | - | No | <input checked="" type="checkbox"/> | Was the examination carried out within an interval of? - 6 Months<br><br>In accordance with an examination scheme?<br><br>After the occurrence of exceptional circumstances? | Yes | <input checked="" type="checkbox"/> | No | -                                   |
|                                                                                                                                                                                        | Yes | - | No | -                                   |                                                                                                                                                                              | Yes | -                                   | No | <input checked="" type="checkbox"/> |

|                                                                                                                                                                                         |              |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|
| Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE                              |              |
| Is the above an existing or imminent danger to persons, Note: This is a reportable defect?                                                                                              | N/A          |
| Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)                                                                                 | Yes by : N/A |
| Particulars of any repair, renewal or alteration required to remedy the defect identified above : N/A                                                                                   |              |
| Particulars of any tests carried out as part of the examination (if none state NONE) : NONE                                                                                             |              |
| <b>Observation/additional comments relative to this thorough examination :</b><br><b>Visual and functions checks conducted at the time of inspection machine was found satisfactory</b> |              |



☒ **Safe to operate**  
Next Inspection: 30-01-2026

Inspected by: Mohamed Askar Ali



For confirmation scan QR code

Search with report number : **ESICO-LFT-R25-4971**