



شركة مساندة الإعمار للفحص Emaar Support Inspection Co.

6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817

Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444

Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

CERTIFICATE OF THOROUGH EXAMINATION OF DIESEL GENERATOR MACHINE

Date of thorough examination : 26-03-2025		Date of issue : 27-03-2025		Report No. : ESICO-LFT-R25-3732	
Name & Address of employer		Location		Sticker No	Standards
SUDHIR EQUIPMENT RENTALS		P 3 SEVEN KHOBAR		5384	ISO -8528
Equipment Identification No	Equipment Description	Safe Working Load(s)	Date of Manufacture	Manufacturer Name	
SG-628-60 OR VEPL/2022-23/023	DIESEL GENERATOR CLASS: H RATED POWER FACTOR: 0.8 FREQUENCY: 60Hz VOLTAGE: 400V RATING: 24KW PHASE: 3	62.5 KVA	06/2022	VARADA ENERGIES PVT. LTD	
Is this the first examination after installaton or assembly at a new site or location? Yes ☐ - ☐ No ☒		Was the examination carried out within an interval of? - 6 Months In accordance with an examination scheme? Yes ☒ No ☐ - ☐ After the occurence of exceptional circumstances? Yes ☐ - ☐ No ☒			
If the answer to the above question is YES, has the equipment been installed correctly? Yes ☐ - ☐ No ☐ - ☐					
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE					
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?					No
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)				Yes by : N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above : NONE					
Particulars of any tests carried out as part of the examination (if none state NONE) : FUNCTIONAL TEST					
Observation/additional comments relative to this thorough examination : The equipment mentioned above poses no threat to users. consult manual for safe use					



For confirmation scan QR code
search with report number : ESICO-LFT-R25-3732

☒ Safe to operate

Next Inspection : 25-09-2025

Inspected by : HENDRICKS



EP-Q4634



1100004098



33564



10739



001052261



05022531



05022531



05022531



05022531