


☐ Interim
☒ Final

INSPECTION REPORT

NO. R104220801.12

BV Job nr: KHO.IVS.19.082.SA

PROJECT: Third Party Inspection for GENERAITOR

Ref: KHO.IVS.19.082.SA

BV Client: SUDHIR

P/o nr: N/A
(client to BV)

Manufacturer: CUMMINS

P/o nr: N/A
(client to Manufacturer)

SUPPLY / SUBJECT OF INSPECTION	SN / TAG Nr	Owner ID No.:	QTY
VISUAL EXAMINATION AND FUNCTIONAL TEST OF GENERAITOR	VEPL/2022-23/027	SG-636-500	1

DOCUMENTS OF REFERENCE : See continuation sheet for additional documents: ☐ Yes ☐ No

Title	Reference n°	Rev.	Approved by	Date
ORIGINAL DECLARATION OF CONFORMITY	-	-	-	-

INSPECTIONS :

Inspection place & Date or Period:

SUDHIR

01 AUG 2022

Stage of inspection :

- ☐ Before manufacturing
☐ During manufacturing
☒ Final
☐ Packing

Type of inspection:

- ☐ Pre-inspection meeting
☐ Document and QC record review
☒ Visual examination, checks
☐ Witnessing tests
☐ Manufacturing progress status
☐ Vendor assessment
☒ Final inspection
☐ Packing

(for details see continuation sheet)

Stamping:☒ NoResults of inspection : ☒ Satisfactory ☐ UnsatisfactoryNon Conformities Reports (NCR):

o NCR's issued during reported period : N/A

o List of outstanding NCR's : N/A

Main Conclusions & Remarks: (for details see continuation sheet)Third party visual inspection of 1 unit of **GENERAITOR** was carried out and found satisfactory at the time of Inspection.

Valid Sticker Number : 01-33609

Next visit scheduled: 31 JULY 2023


☐ Interim
☒ Final

INSPECTION REPORT

NO. R104220801.11

BV Job nr: KHO.IVS.19.082.SA

Description of the inspections carried out:**1. Introduction:**

The undersigned surveyor to Bureau Veritas acting within the scope of work along with the General condition which Regulate the intervention of the society IVS-Lifting/B&F Department at the Request of SUDHIR on the purpose of Third Party Inspection .

2. Scope of Inspection :a. Visual Inspection & Functional Test of **GENERAITOR****1- General Data**

Equipment Type	GENERAITOR
Manufacturer	CUMMINS
Model	VEPL-500-CDP
Serial No.	VEPL/2022-23/027

2- Inspection and Test Results

Acceptance criteria	Result	Remarks
1. Document review (Original Declaration of Conformity)	Pass	Available
2. Visual inspection of Unit, wear, damage, loose connection /components, corrosion.	Pass	Found good condition.
3. Electrical,(conduct general inspection of wiring and connection cable termination, corrosion, damage	Pass	Found good condition.

➤ Conclusion:The **GENERAITOR** found in good condition at the time of Inspection.

Inspected by:
MOHAMMED ALHOMUD
 EQUIPMENT INSPECTOR

Checked by:
 OPERATION TEAM LEADER

Issued at Al Khobar office on **02 AUG 2022**