



Client Name & Address:	Sudhir Equipment Rental Company		
Work Order No.	ZAM-4059-11-23	Report No.	ZAMIL-R08061 / VIS
Place Of Inspection	DAMMAM DAMMAM	Report Date	23/11/2023
Date of Last Inspection	01 APRIL 2023	Date of Inspection	20/11/2023
Customer Requisition No.	N/A	Date of Next Inspection	19/05/2024
Applicable Standards	ISO 8528-3-2020	Issued Sticker No.	ZAM-W-14864
O.E.M / C.O.C No. / Drawings	VARADA / VEPL-250-CDP	Color Code (If Applicable)	NA
Equipment Used	N/A	Model No.	VEPL-250-CDP

Equipment Serial No.	Equipment I.D	QTY	Description	Capacity/SWL (Ton)
VEPL/2022-23/254	SG-806-300	01	DIESEL GENERATOR MANUFACTURE : VARADA MODEL NO : VEPL-250-CDP ALTERNATOR NO : N22L510259 ENGINE NO : 3008602364 RATING : 300 KVA Note : Visual inspection and functional test has been performed on the above mentioned equipment, during the time of inspection no any abnormality found.	300 KVA

Is this the first examination after installation or assembly at a new site or location:	☐ YES ☒ NO
If the answer to the above question is YES. Has the equipment been installed correctly?	☐ YES ☐ NO ☒ NA
Was the thorough examination carried out Within an interval of 3 months?	☐ YES ☒ NO
Was the thorough examination carried out Within an interval of 6 months?	☒ YES ☐ NO
Was the thorough examination carried out Within an interval of 12 months?	☐ YES ☒ NO
In accordance with an examination scheme?	☒ YES ☐ NO
After the occurrence of exceptional circumstances?	☐ Yes ☒ No
Identification of any part found to have a defect which is or could become a danger to person and a description of the defect (if none state none): NONE	
Is the above a defect which is of immediate danger to persons	☐ YES ☒ NO
Is the above a defect which is not yet but could become a danger to persons? (If yes state the day by when)	☐ YES ☒ NO Date:
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE	
Particulars of any tests carried out as part of the examination: (If none state NONE): NONE	
Inspection Result:	During the time of Inspection Result found satisfactory - Is this Equipment Safe to Operate? ☒ YES ☐ NO
This certificate by company under its general conditions of services. This issuance of this certificate does not exonerate the buyers or sellers from exercising all their rights discharging all their liabilities under the contacts of sale. Stipulations to contrary are not binding on the company's responsibility under this certificate is limited to proven negligence and will in no case be more than ten times the amount of the free or commission. The above findings are limited to date place of intervention only. The company is neither an insurer not a guarantor disclaims all liabilities in such capabilities.	

Inspected By Qualified: LEEA & ASNT NDT Level II		Reviewed By		Stamp
Name:	Asif Hussain	Name:	Belal Elsayed	
Position:	Inspector	Position:	Technical supervisor	
Signature:		Signature:		



Name and address of employer of persons making and authenticating this report: Zamil Inspection & Contracting Co, King Fahad Road-Al-Dhabab Avenue-Dammam 32261
C.R.: 2050069798-Email: operations@zamil.sa



Zamil Inspection & Contracting Co.



+966555052687



info@zamil.sa



NO. ZAM-W-14864

Equipment Type : DIESEL GENERATOR
capacity/SWL : 300 KVA
Equipment ID : SG-806-300
Equipment S.N. : VEPL/2022-23/254
Inspection Date : 20/11/2023
Next Insp Date : 19/05/2024
Inspected By : Asif Hussain



Corporate Partner