OWNERSHIP CERTIFICATE

To Whom It May Concern

This is to certify that the following equipment listed below is the sole property of Sudhir Equipment Rental Company:

Equipment	**AWP**
Brand / Make	**Genie**
Asset ID	**S28SG-489**
Model Number	**S85**
Serial Number	**S85D-710**
Working Height	**28 Meter**
Type	**Diesel Telescopic Boom**
Manufacturing Year	**2018**

This certification is issued to confirm the ownership status of the aforementioned equipment. Sudhir Equipment Rental Company holds full legal ownership rights over the listed equipment and retains all associated benefits and responsibilities.

Should there be any queries or requests for verification regarding the ownership of the mentioned equipment, please do not hesitate to contact us at: Info@sudhirrentals.com

Sincerely,

شركة سودهير لتأجير المعدات
الدمام
س.ت ٢٠٥٠١٣٠٠٥٣
C.R. 2050130053
Dammam
SUDHIR EQUIPMENT RENTAL COMPANY

Rajesh Thakur
Plant Manager
Sudhir Equipment Rental Company

Certificate of Insurance

Policy Holder Name	Sudhir Equipment Rental Company	**اسم حامل الوثيقة**
Policy Number	5/EP/30425/0/0	**رقم الوثيقة**
Original Policy Period	05/04/2026 to 04/04/2027	**فترة الوثيقة الأصلية**

Gulf Insurance Group certifies that above client is holding Contractor's Plant & Machinery Insurance Policy for the below mentioned Equipment in accordance with the above mentioned Insurance Policy:

تشهد مجموعة الخليج للتأمين بأن العميل المذكور أعلاه يحمل وثيقة تأمين على معدات والات المقاولين للمعدة المذكورة أدناه, و ذلك وفقا لشروط وثيقة التأمين المذكورة أعلاه:

Asset ID	:	S28SG-489	:	**معرف الأصل**
Brand	:	Genie	:	**العلامة التجارية**
Type	:	S85	:	**النوع**
Model	:	AWPS	:	**الطراز**
Manufacturing Year	:	0	:	**سنة الصنع**
Equipment Serial Number	:	S85D-710	:	**الرقم التسلسلي للمعدة**
Insurance Effective Date	:	05/04/2026	:	**تاريخ سريان التأمين**

This Certificate has been issued upon Insureds request as per all terms and conditions, exclusions, warranties mentioned in the policy.

تم اصدار هذة الشهادة بناء على طلب المؤمن له وذلك حسب الشروط والاستثناءات والاشتراطات المذكورة في الوثيقة

Al Khobar : 01st April 2026

Signature of Insurer's Authorized Representative

PUBLIC

الشركة العالمية لخدمات التفتيش المحدودة

UNIVERSAL INSPECTION CO. LTD.

LEEA Full Member

CERTIFICATE OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination	Date of Certificate	Certificate number	Sticker Number(s)
26-Jul-2026	26-Jul-2026	DUB-L-1073	DUB/000773
Next Examination Due Date	**Date of last thorough Examination**	**Reference Standard**	**Order No**
25-Jan-2027	22-01-2026	BS EN 280-1:2022	W.O-DUB-LIF-26072026-002

Name and Address of Customer	Address of Examination
SUDHIR EQUIPMENT RENTAL COMPANY Duba-Kingdom of Saudi Arabia	Amaala-Kingdom of Saudi Arabia

Description and identification of the equipment	Equipment ID	Safe Working Load
MANLIFT (Telescopic Boom Lift) Manufacture: JLG Model: 660SJ / M.f.g Year: 2024 Sr. No: B300013089, Max Platform Height: 20.02m, Horizontal Outreach: 17.40m, Unrestricted Capacity: 250 kg (2 Person), Max. wind speed: 12.5 m/s, G.V.W: 12020 Kg.	S22SJ-1186	340 Kg (3 Person)

Is this first Examination after installation or assembly at new site or location?	NO	**Was the Examination carried out within an interval of 6 months?**	YES
Has the equipment been installed correctly?	YES	**Was the Examination carried out within an interval of 12 months?**	NO
In accordance with an Examination Scheme?	NO	**After the occurrence of exceptional circumstances?**	NO

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

N/A

Is the above an existing or imminent danger to persons?	NO
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when)	NONE

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

N/A

Particulars of any tests carried out as part of the examination. And standard applied.

This ManLift has been Visual, Functional Examined in accordance with BS EN 280-1:2022.

Load Test(s): N/A

QA/QC

IS THIS EQUIPMENT SAFE TO OPERATE?	YES
Name and Signature of the person issue this certificate.	Name and Signature of the person authenticating this certificate.
Name: MUHAMMED SUHAIL.CK	Name: REMON RAJ
Signature:	Signature:

Comments: At the time of inspection, the equipment was found satisfactory and free from any defects or damage and found safe for use. UNIVERSAL INSPECTION CO. LTD. holds no responsibility for any damage occurring after the inspection date due to improper use pertaining to operation as per the manufacturer's manual maintenance, and servicing. This Thorough Examination was within the limits of Client's specifications.

P.O Box no. 2072, Jubail-31951, KSA
Tel.: +966 13 344 8882/Fax.: +966 13 344 8881
Tel.: +966 13 367 0515
Website: www.ui.com.sa

ص.ب 2072 - الجبيل 31951 - المملكة العربية السعودية
+هاتف: 8882 344 13 966+ / فاكس: 8881 344 13 966
+هاتف: 0515 367 13 966
الموقع الالكتروني www.ui.com.sa

The PDF document is electronically generated and digitally signed

Checklist

Certificate/Report Number: DUB-L-1073
Sticker Number(s): DUB/000773

INSPECTION POINTS	Pass	Fail	N/A
Last Third-party inspection Certificate	☑	☐	☐
Last Third-party inspection sticker	☑	☐	☐
Operator Iqama/License/ Third Party	☑	☐	☐
Vehicle documents (Insurance & Estamara)	☑	☐	☐
Tire and air pressure	☑	☐	☐
Level Indicators	☑	☐	☐
Lights (include beacon light)	☑	☐	☐
Horn/ Reverse alarm	☑	☐	☐
Electrical switches and gauges	☑	☐	☐
Emergency lowering system	☑	☐	☐
Safety signs, labels and stickers	☑	☐	☐
Platform condition	☑	☐	☐
Greasing & lubrication of boom	☑	☐	☐
Overload Indicator	☑	☐	☐
Safe Access & Egress	☑	☐	☐
Fire extinguisher in good condition & valid	☑	☐	☐
Engine oil level, check system for damage, leak	☑	☐	☐
Hydraulic oil level, check system for leaks	☑	☐	☐
Transmission oil	☑	☐	☐

INSPECTION POINTS	Pass	Fail	N/A
Air filter	☑	☐	☐
Steering oil and steering system/Joystick	☑	☐	☐
Brakes and brake system (including parking brake)	☑	☐	☐
Fuel level and check for leaks in fuel system	☑	☐	☐
Coolant	☑	☐	☐
Radiator and hoses	☑	☐	☐
Fan belts and pulleys	☑	☐	☐
Hoses and fittings	☑	☐	☐
Battery	☑	☐	☐
Air Conditioner/Heater	☐	☐	☑
Boom lift, Boom extension & retraction (deflection)	☑	☐	☐
Lever controls & pedals	☑	☐	☐
Slewing mechanism	☑	☐	☐
Boom cylinder/Lifting cylinder	☑	☐	☐
Pneumatic system	☑	☐	☐
Identification & SWL Marking	☑	☐	☐
Hydraulic system	☑	☐	☐
Outrigger Jacks	☐	☐	☑
Operation	☑	☐	☐

Comments/Remarks:

N/A

Reference Documents:

BS EN 280-1:2022.

QA/QC

Inspected & witnessed by: MUHAMMED SUHAIL.CK

Signature:

Approved by: REMON RAJ

Signature:

The PDF document is electronically generated and digitally signed

الشركة العالمية لخدمات التفتيش المحدودة
UNIVERSAL INSPECTION CO. LTD.
LEEA Full Member

CERTIFICATE OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination	Date of Certificate	Certificate number	Sticker Number(s)
26-Jul-2026	26-Jul-2026	DUB-L-1074	DUB/000774
Next Examination Due Date	**Date of last thorough Examination**	**Reference Standard**	**Order No**
25-Jan-2027	29-01-2026	BS EN 280-1:2022	W.O-DUB-LIF-26072026-002

Name and Address of Customer	Address of Examination
SUDHIR EQUIPMENT RENTAL COMPANY Duba-Kingdom of Saudi Arabia	Amaala-Kingdom of Saudi Arabia

Description and identification of the equipment	Equipment ID	Safe Working Load
MANLIFT (Telescopic Boom Lift) Manufacture: GENIE Model: S-85 / M.f.g Year: 2018 Sr. No: S85D-710, Max Platform Height: 25.91m, Horizontal Outreach: 23.32m, Diesel Engine: Terex, 55 kW Max. wind speed: 12.5 m/s, G.V.W: 17365 Kg.	S28SG-489	227 Kg (2 Person)

Is this first Examination after installation or assembly at new site or location?	NO	**Was the Examination carried out within an interval of 6 months?**	YES
Has the equipment been installed correctly?	YES	**Was the Examination carried out within an interval of 12 months?**	NO
In accordance with an Examination Scheme?	NO	**After the occurrence of exceptional circumstances?**	NO

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

N/A

Is the above an existing or imminent danger to persons?	NO
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when)	NONE

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

N/A

Particulars of any tests carried out as part of the examination. And standard applied.

This ManLift has been Visual, Functional Examined in accordance with BS EN 280-1:2022.

Load Test(s): N/A

IS THIS EQUIPMENT SAFE TO OPERATE?	YES
Name and Signature of the person issue this certificate.	Name and Signature of the person authenticating this certificate.
Name: MUHAMMED SUHAIL.CK	Name: REMON RAJ
Signature: Suhail CK	Signature: Remon Raj. C

QA/QC
الشركة العالمية لخدمات التفتيش المحدودة
UNIVERSAL INSPECTION CO. LTD.

Comments: At the time of inspection, the equipment was found satisfactory and free from any defects or damage and found safe for use. UNIVERSAL INSPECTION CO. LTD. holds no responsibility for any damage occurring after the inspection date due to improper use pertaining to operation as per the manufacturer's manual maintenance, and servicing. This Thorough Examination was within the limits of Client's specifications.

P.O Box no. 2072, Jubail-31951, KSA
Tel.: +966 13 344 8882/Fax.: +966 13 344 8881
Tel.: +966 13 367 0515
Website: www.ui.com.sa

ص.ب 2072 - الجبيل 31951 - المملكة العربية السعودية
+هاتف: 966 13 344 8882 / فاكس: 966 13 344 8881
+هاتف: 966 13 367 0515
الموقع الالكتروني www.ui.com.sa

The PDF document is electronically generated and digitally signed

Checklist

Certificate/Report Number: DUB-L-1074
Sticker Number(s): DUB/000774

INSPECTION POINTS	Pass	Fail	N/A
Last Third-party inspection Certificate	☑	☐	☐
Last Third-party inspection sticker	☑	☐	☐
Operator Iqama/License/ Third Party	☑	☐	☐
Vehicle documents (Insurance & Estamara)	☑	☐	☐
Tire and air pressure	☑	☐	☐
Level Indicators	☑	☐	☐
Lights (include beacon light)	☑	☐	☐
Horn/ Reverse alarm	☑	☐	☐
Electrical switches and gauges	☑	☐	☐
Emergency lowering system	☑	☐	☐
Safety signs, labels and stickers	☑	☐	☐
Platform condition	☑	☐	☐
Greasing & lubrication of boom	☑	☐	☐
Overload Indicator	☑	☐	☐
Safe Access & Egress	☑	☐	☐
Fire extinguisher in good condition & valid	☑	☐	☐
Engine oil level, check system for damage, leak	☑	☐	☐
Hydraulic oil level, check system for leaks	☑	☐	☐
Transmission oil	☑	☐	☐

INSPECTION POINTS	Pass	Fail	N/A
Air filter	☑	☐	☐
Steering oil and steering system/Joystick	☑	☐	☐
Brakes and brake system (including parking brake)	☑	☐	☐
Fuel level and check for leaks in fuel system	☑	☐	☐
Coolant	☑	☐	☐
Radiator and hoses	☑	☐	☐
Fan belts and pulleys	☑	☐	☐
Hoses and fittings	☑	☐	☐
Battery	☑	☐	☐
Air Conditioner/Heater	☐	☐	☑
Boom lift, Boom extension & retraction (deflection)	☑	☐	☐
Lever controls & pedals	☑	☐	☐
Slewing mechanism	☑	☐	☐
Boom cylinder/Lifting cylinder	☑	☐	☐
Pneumatic system	☑	☐	☐
Identification & SWL Marking	☑	☐	☐
Hydraulic system	☑	☐	☐
Outrigger Jacks	☐	☐	☑
Operation	☑	☐	☐

Comments/Remarks:

N/A

Reference Documents:

BS EN 280-1:2022.

QA/QC

Inspected & witnessed by: MUHAMMED SUHAIL.CK

Signature:

Approved by: REMON RAJ

Signature:

The PDF document is electronically generated and digitally signed