

INSPECTION CERTIFICATE

MANLIFT

CLIENT NAME : SUDHIR EQUIPMENT RENTAL CO		WORK ORDER : WR-YAS-428	
EQUIPMENT DESCRIPTION : MANLIFT WITH ARTICULATED BOOM WITH MAXIMUM WORKING HEIGHT OF 20.46 M		CERTIFICATE NO : YAS-CRT-1923	
		STICKER NO : 13715	
DATE OF INSPECTION : 06-Oct-2026		NEXT INSPECTION DUE : 05-Apr-2027	
PREVIOUS INSPECTION :		PREVIOUS INSPECTION DETAILS :	
MANUFACTURER : JLG		MODEL/TYPE : 600AJ	
SERIAL NO : 0300238067		OWNER ID : S20AJ-429	
CHECKLIST NO. : 1584		MANUFACTURED YEAR : 2018	
TYPE OF INSPECTION : PERIODIC AND FUNCTIONAL INSPECTION		LOCATION : RIYADH	
REFERENCE STANDARDS : BS EN 280-1:2022			
CAPACITY / SWL:	227 KG		
NO OF PERSONS:	2 PERSONS		
TEST LOAD:	N/A		
MAX HORIZONTAL REACH:	12.10 M		
PLATFORM HEIGHT:	18.46 M		
OUTRIGGER:	N/A		
Is this the first examination after installation or assembly at a new site or location ?	☐ Yes ☒ No	Within an interval of Months?	☒ 6 ☐ 12
If the answer to the above question is YES has the equipment been installed correctly ?	☐ Yes ☒ No	In accordance with an examination scheme ?	☐ Yes ☒ No
After the occurrence of exceptional circumstances ?		☐ Yes ☒ No	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE)		NONE	
Is the above a defect which is of immediate danger to persons		☐ Yes ☒ No	
Is the above a defect which is not yet but could become a danger to persons:(If YES state the date by when)		NONE	
Particulars of any tests carried out as part of the examination: (If none state NONE)		NONE	
RESULT:	☒ PASS ☐ FAIL	IS THIS EQUIPMENT FIT FOR PURPOSE?	☒ Yes ☐ No
REMARKS/RECOMMENDATION THIS IS TO CERTIFY THAT THE MANLIFT HAS BEEN PERIODICALLY AND FUNCTIONALLY INSPECTED IN ACCORDANCE WITH INTERNATIONALLY RECOGNIZED STANDARDS ON THE INSPECTION DATE. THE EQUIPMENT IS FREE FROM EXTERNAL DAMAGE, AND THE EQUIPMENT IS FOUND TO BE IN SATISFACTORY CONDITION.			
Date Of Report: 6/10/2026			

Approved By : ABDUL HALEEM

Authorized Inspector : AHAMED

WORKORDER NO: WR-YAS-428
CERTIFICATE NO: YAS-CRT-1923
WORKORDER NO: WR-YAS-428
CERTIFICATE NO: YAS-CRT-1923
WORKORDER NO: WR-YAS-428
CERTIFICATE NO: YAS-CRT-1923



WORKORDER NO: WR-YAS-428
CERTIFICATE NO: YAS-CRT-1923
WORKORDER NO: WR-YAS-428
CERTIFICATE NO: YAS-CRT-1923
WORKORDER NO: WR-YAS-428
CERTIFICATE NO: YAS-CRT-1923

Note : This certificate becomes void if the equipment is altered, repaired, or modified without authorization. The equipment owner is solely responsible for safe operation and maintenance. The company accepts no liability for damages or failures arising from negligence, poor maintenance, or conditions not detectable during routine inspection.