

Certificate of Visual Examination

Client Name :		
Sudhir Equipment Rental Company		
Work/ Rig Location:	Certificate Number:	Issued Sticker No.(if Applicable)
Dammam	ZAM-040-21- 208	W.6380
Date of Last Inspection	Date of Inspection:	Date of Next Inspection:
New	10-Apr-2021	9-Apr-2022
Relevant Standards:	O.E.M / C.O.C / Reverse Engineering Cert. No.	Color Code (If Applicable for the item) (Current applicable Color at the Time of Inspection)
ANSI/ITSDF B56.6	30D-7SA	
Zamil Ref No.	Customer Requisition No.	N/A
ZAM-0206-04-21	SG-EPO-2020-0148	

I.D. NUMBER	QTY	DESCRIPTION	SWL / CAPACITY
HHKCHN55PM000105 7	01	Fork Lift Diesel Power Model : 30D-7SA ID : S3FLT-019 Manufacture : HYUNDAI 2020 Engine S/N : 345571 Engine Model : S4S-DPEU2 Capacity : 2650 Kg At Load Center : 500 mm Weight : 4650 Kg Location : SUDHIR Yard NOTE : Visual Inspection & Functional Test Were Carried Out On The Above Mentioned Equipment , At The Time Of Inspection No Any Abnormality Found.	3 Ton

Result: During the Time of Visual Inspection, Result found Satisfactory.

This Certificate by Company Under Its General Conditions of Services. This Issuance of This Certificate Does Not Exonerate the Buyers or Sellers from Exercising All Their Rights Discharging All Their Liabilities Under the Contacts of Sale. Stipulations to Contrary Are Not Binding on The Companies Responsibility Under This Certificates Is Limited to Proven Negligence and Will in No Case Be More Than Ten Times the Amount of The Free or Commission. The Above Findings Are Limited to Date Place of Intervention Only. The Company Is Neither an Insurer Not a Guarantor Disclaims All Liabilities in Such Capabilities.

Inspected By:
Name : Mohamed Youssry
Qualifications : LEAA & ASNT NDT Level II Certified
Signature & Stamp:


 ISO 9001
TUV NORD

DROPS



طريق الملك فهد - حي الضباب - الدمام - س.ت: 2050069798 - ص.ب 419 - الدمام 31411

King Fahad Road - Al-Dhabab Avenue - Dammam - C.R.: 2050069798 - P.O. Box 419 - Dammam 31411 Email: info@zamil.sa

Yasser/REV01/02-2