



Report of Thorough Examination of Forklift Truck

Report No:	TEST-369-32210-06	Report Issue Date:	25 January 2025
Work Order No:	32210	Inspection Type:	Periodic Visual & Functional
Customer Name:	Sudhir Equipment Rental Co.		
Work Location:	Dammam Yard	Equipment Type:	Forklift Truck
Standard Reference:	ANSI B56.1 & ANSI B56.6	Manufacturer:	HANGCHA
Inspection Date:	25 January 2025	Equipment Model:	CPCD30-AW10
Next Inspection Date:	24 July 2025	Sticker No:	53282
Measuring & Testing Equipment used:	Wear caliber (WC-003) , Measuring Ruler (TR-10)		

Serial No.	Description	SWL	Reason For Examination	Result	Safe To Use
14BD11689	DIESEL-POWERED FORKLIFT TRUCK EQUIPMENT ID: S3FLT-057 SWL: 3000 kg @500 mm LOAD CENTER MAX.LIFTING HEIGHT: 4500 mm ENGINE POWER: 35.4 kW / 2500 r/min WEIGHT: 4560 kg LOCATION: SUDHIR YARD.	3000 kg	B	Accepted	Yes

Reason For Exam.	A- 3 Months	B- 6 Months	C- 12 Months	D- Written Scheme	E- Exceptional Circumstance	F- Installation
Result	ACCEPTED			REJECTED (See Attached Defect Report)		

I hereby declare that the above information is correct and that the equipment has been thoroughly examined as far as possible in accordance with the appropriate provisions and that at the time of the examination is found to be free from any defect likely to affect safety.

Inspected By:	Sheik Mujibur Rahman	Approved By:	Mostafa Sharshar
Signature		Designation:	Lifting Technical supervisor
		Signature:	

No liability will be considered against TEST company for failure or damage to other occurrence to Client owned or operated equipment due to misuse, improper installations, poor maintenance, weather/environmental conditions & equipment operator/user mistakes or uncontrolled operation & maintenance.

This Inspection Certificate/Report shall not be reproduced except in full without the approval of TEST Company and the Client.



Testing Equipment Specialist Team Company

Dammam 34261- Saudi Arabia +966 13 808 4277 sales@testcosa.com www.testcosa.com

Forklift Truck Inspection Checklist

Customer Name:	Sudhir Equipment Rental Co.		
Report No:	TEST-369-32210-06	Report Issue Date:	25 January 2025
Work Order No:	32210	Work Location:	Dammam Yard
Standard Reference:	ANSI B56.1 & ANSI B56.6	Equipment Type:	Forklift Truck
Inspection Date:	25 January 2025	Equipment Serial No.:	14BD11689

ID	Item	Pass	Fail	N/A	Comments
1	Equipment Documentation is available	✓			
2	Previous Inspection Report was checked	✓			
3	Equipment is operated by a qualified operator	✓			
4	Warning notice ,cautions or restrictions for safe operation and maintenance log are displayed	✓			
5	Manufacturer name, serial no. and model are clearly marked or tagged.	✓			
6	Safe Working Load was clearly marked on forklift	✓			
7	Maximum Travel Height was clearly marked	✓			
8	The equipment is free of defective and/or corroded members/ Joints	✓			
9	There are no loose nuts ,bolts, missing ,worn or damaged parts around the structure	✓			
10	All fluid levels for oil , water and hydraulic are adequate	✓			
11	Air , water , hydraulic and fuel system not leaking	✓			
12	All moving parts are lubricated	✓			
13	Working environment is hazard free and forklift can work safely	✓			
14	An hour meter is fitted	✓			
15	Fire extinguisher is fitted in its location and check the inspection label / tag	✓			
16	Wheel condition & pressure	✓			
17	Wheel nuts are fully secured	✓			
18	Outriggers boxes are free of cracks, or distortion			✓	
19	Outrigger pad fully secured and in a good condition			✓	
20	Outrigger rams free of oil leakage			✓	
21	Telescopic boom sections is good lubricated			✓	
22	Telescopic boom lifting cylinder is free of oil leakage			✓	
23	Check Forks Identification	✓			
24	Check Forks Positioning Lock	✓			
25	Forks lock condition	✓			
26	Fork Surface is free from visual cracks or damage	✓			
27	Chain fixing points are secured	✓			
28	Check Chain for wear , corrosion	✓			
29	Check Chain Elongation	✓			
30	Mast is free from any damage , corrosion and worn	✓			
31	Mast fixing points are secured	✓			
32	Transmission and Steering condition	✓			
33	Horn is working	✓			

34	Travelling Brake is working in a good condition	✓			
35	Park Brake is working in a good condition	✓			
36	All Tyres are serviceable and without damage or excess wear	✓			
37	Operator seat condition	✓			
38	Seatbelt is fitted and in a good condition	✓			
39	Operator cab overhead guards	✓			
40	Reverse Travel alarm is operational	✓			
41	Lights condition	✓			
42	Battery is secure , guarded and ventilated	✓			
43	Load chart is provided in accessible location	✓			
44	Hydraulic , Coolant and Fuel hoses not leaking	✓			
45	Engine Gauges and associated indicators are working in a good condition	✓			
46	Engine Mounting have not gone soft with oil contamination	✓			
47	Turning Signals and indicators are working correctly	✓			
48	Travel control are properly operating	✓			
49	Marking and directions for all control levers are clearly displayed	✓			
50	Mirrors condition	✓			
51	Difference in the tip height not exceed 3% of the blade length	✓			
52	No deviation in fork Angle (Upper Face of Blade to Load Face of the Shank) of greater than 3 degrees from the original spec.	✓			
53	Reduction in thickness of the blade and shank less than 10% of the original thickness	✓			
54	Deviation in straightness of front face of the shank not exceed 0.5% Of the shank height	✓			
55	Deviation in straightness of the upper face of the blade not exceed 0.5% Of the blade length	✓			
56	General condition	✓			