# OWNERSHIP CERTIFICATE

## To Whom It May Concern

This is to certify that the following equipment listed below is the sole property of Sudhir Equipment Rental Company:

| | |
|---|---|
| **Equipment** | **Scissorlift** |
| **Brand / Make** | **DINGLI** |
| **Asset ID** | **SD18SL-2430** |
| **Model Number** | **JCPT1823RTL2** |
| **Serial Number** | **JPR0025D00261** |
| **Working Height** | **18 Meter** |
| **Type** | **Diesel Scissor Lift** |
| **Manufacturing Year** | **2025** |

This certification is issued to confirm the ownership status of the aforementioned equipment. Sudhir Equipment Rental Company holds full legal ownership rights over the listed equipment and retains all associated benefits and responsibilities.

Should there be any queries or requests for verification regarding the ownership of the mentioned equipment, please do not hesitate to contact us at: Info@sudhirrentals.com

Sincerely,

شركة سودهير لتأجير المعدات
الدمام
س.ت ٢٠٥٠١٣٠٠٥٣
C.R. 2050130053
Dammam
SUDHIR EQUIPMENT RENTAL COMPANY

**Rajesh Thakur**
Plant Manager
Sudhir Equipment Rental Company

# Certificate of Insurance

| | | |
|---|---|---|
| **Policy Holder Name** | Sudhir Equipment Rental Company | **اسم حامل الوثيقة** |
| **Policy Number** | 5/EP/30425/0/0 | **رقم الوثيقة** |
| **Original Policy Period** | 05/04/2026 to 04/04/2027 | **فترة الوثيقة الأصلية** |

Gulf Insurance Group certifies that above client is holding Contractor's Plant & Machinery Insurance Policy for the below mentioned Equipment in accordance with the above mentioned Insurance Policy:

**تشهد مجموعة الخليج للتأمين بأن العميل المذكور أعلاه يحمل وثيقة تأمين على معدات والات المقاولين للمعدة المذكورة أدناه, و ذلك وفقا لشروط وثيقة التأمين المذكورة أعلاه:**

| | | | | |
|---|---|---|---|---|
| Asset ID | : | SD18SL-2430 | : | **معرف الأصل** |
| Brand | : | DINGLI | : | **العلامة التجارية** |
| Type | : | JCPT1823RTL2 | : | **النوع** |
| Model | : | AWPS | : | **الطراز** |
| Manufacturing Year | : | 2025 | : | **سنة الصنع** |
| Equipment Serial Number | : | JPR0025D00261 | : | **الرقم التسلسلي للمعدة** |
| Insurance Effective Date | : | 05/04/2026 | : | **تاريخ سريان التأمين** |

This Certificate has been issued upon Insureds request as per all terms and conditions, exclusions, warranties mentioned in the policy.

**تم اصدار هذة الشهادة بناء على طلب المؤمن له وذلك حسب الشروط والاستثناءات والاشتراطات المذكورة في الوثيقة**

Al Khobar : 01st April 2026

Signature of Insurer's Authorized Representative

PUBLIC

# CERTIFICATE OF TEST AND THOROUGH EXAMINATION OF ELEVATION WORK PLATFORM

| Cert. No.: 2282745 | Date of Examination: 01/08/2026 | Sticker No.: 01-100936 |
|---|---|---|

| | | |
|---|---|---|
| Name & address of owner of the equipment | | Sudhir Equipment Rental Company |
| Inspection requested by | | Sudhir Equipment Rental Company |
| Place of inspection | | Dammam Yard |
| Type of inspection | | Visual Inspection And Function Test |
| Relevant regulation / Standard | | ANSI 92.6 |
| Date of previous inspection / load test | | |
| Identification & Description of the Equipment | Manufacturer name | Dingli |
| | Equipment Type | Self-Propelled Elevation Platform ( Scissor Lift ) |
| | Model / Year | JCPT1823RTL2 / 2025 |
| | Serial number | JPR0025D00261 |
| | Owner ID / Registration number | SD18SL-2430 |
| | Nature of power | Diesel |
| | Rated Capacity (SWL) | 680 Kg |
| | Max. Platform height: | 18 Mtr |
| | Max. Horizontal reach: | - |

| Description of test: | TEST LOAD | S.W.L. |
|---|---|---|
| - Visual Inspection And Function Test Was Carried Out<br>- And Found No Defects And Satisfactory At The Time Of Inspection | - | 680Kg |

**Result of Examination:**
**The above mentioned equipment has been found satisfactory at the time of inspection and is considered to be safe for further use, subject to continuous maintenance being applied and qualified operator being employed.**

This is to certify that the Competent Person did attend at the said premises on said date to witness proof load test and/or to carry out thorough examination of the equipment described herein and that all particulars described above were correct at the time of examination. This Certificate becomes void in case of any major repair, modification and /or alteration being un-authorized by issuer of hereof.

| Next Proof Load Test Due: After Major Repair/Modifications | Next Inspection Due is on or before: 31/01/2027 |
|---|---|

Issued at Al Khobar on 01/08/2026
Inspector to Bureau Veritas
Signature:

Name: Mohamed Elsabry
Position: Inspector

BUREAU VERITAS IN SERVICE VERIFICATION 09 EASTERN REGION SAUDI ARABIA

Reviewed by
Signature:

Name: Ahmed Elabady
Position: Reviewer

The technical conclusions thus expressed may have to be reconsidered in light of any modifications or alterations that would invalidate the data shown in the present certificate. These conclusions would become null & void should Bureau Veritas not be kept informed of such modifications or alterations with specific reference to the present certificate.
Any person not a party to the contract pursuant to which this document is delivered may not assert a claim against Bureau Veritas for any liability arising out of errors or omissions which may be contained in said document, or for errors of judgement, fault or negligence committed by the personnel of the Society or of its Agents in the establishment or issuance of this document, and in connection with any activities for which it may provide.
This not is NOT an indication that the item(s) is (are) fir for any specific purpose and does not release the manufacture, supplier and any party from their respective duty, guarantee, obligation and/or indemnity relating to, without limitation patents, workmanship, materials, safety, performance in operation and/or reliability.

## CHECKLIST OF TEST AND THOROUGH EXAMINATION OF ELEVATION WORK PLATFORM

| SECTION | CONDITION/REMARKS |
|---|---|
| **1. ACCESS** | |
| 1.1 Access to the cabin/control station | Satisfactory |
| 1.2 Access for maintenance operation | Satisfactory |
| **2. STRUCTURE OF EQUIPMENT** | |
| 2.1 Boom sections | Not applicable |
| 2.2 Bolts & rivets | Satisfactory |
| 2.3 Connecting pins | Satisfactory |
| 2.4 Chassis structure | Satisfactory |
| 2.5 Platform condition | Satisfactory |
| 2.6 Sheaves & pins | Satisfactory |
| 2.7 Mounting bolts | Satisfactory |
| 2.8 Tyres / Crawler | Satisfactory |
| 2.9 Markings of operation controls | Satisfactory |
| 2.10 Outriggers / Stabilizers | Satisfactory |
| **3. HYDRAULIC SYSTEM** | |
| 3.1 Cylinder | Satisfactory |
| 3.2 Motors/ Power Train | Satisfactory |
| 3.3 Hydraulic Pump | Satisfactory |
| 3.4 Tank & oil | Satisfactory |
| 3.5 Hoses | Satisfactory |
| 3.6 Steering system | Satisfactory |
| **4. POWER UNIT** | |
| 4.1 Engine | Satisfactory |
| 4.2 Spark arrestor | Not applicable |
| 4.3 Operator control panel | Satisfactory |
| 4.4 Gear boxes | Satisfactory |
| **5. SLEW UNIT** | |
| 5.1 Rack & pinion | Not applicable |

| | |
|---|---|
| 5.2 Bearings | Not applicable |
| 5.3 Bearing bolts | Not applicable |
| 5.4 Brakes | Not applicable |
| 5.5 Swing lock | Not applicable |
| **6.SAFETY DEVICE** | |
| 6.1 Motion Alarm | Satisfactory |
| 6.2 Auxiliary Power Unit (Emergency Lowering system) | Satisfactory |
| 6.3 Overload protection | Satisfactory |
| 6.4 Limit switches | Satisfactory |
| 6.5 Speed control | Satisfactory |
| 6.6 Emergency stop | Satisfactory |
| 6.7 Fire Extinguisher | Satisfactory |
| 6.8 Tilt Buzzer | Satisfactory |
| 6.9 Rotating warning light | Satisfactory |
| 6.10 Working hours meter | Satisfactory |

Inspector to Bureau Veritas
Signature:






Name: Mohamed Elsabry
Position: Inspector


No. LFT-S.
01 - 100936
BUREAU VERITAS
Saudi Arabia
Tel:+966 13 882 1071
Fax:+966 13 882 1072
EQUIP. NO. SD18SL-2430
EQUIP. S N. JPR0025D00261
S. W. L: 680 Kg
DATE OF INSPECTION 01-Aug-2026
NEXT INSPECTION DUE ON 31-Jan-2027
INSPECTED BY Mohamed Tariq
This sticker is issued under Bureau veritas General Conditions of Service and is valid only in conjunction with hereafter inspection Report No.
Report No. LFT-R
SUDHIR Rentals
Service : 050 999 3274
Technician :