


☐ Interim  
☒ Final

## INSPECTION REPORT

NO. R109220906.05

BV Job nr: KHO.INI.22.SA.

|                                                    |                                         |
|----------------------------------------------------|-----------------------------------------|
| PROJECT: Third Party Inspection for AIR COMPRESSOR | Ref: KHO.INI.22.SA.                     |
| BV Client: SUDHIR RENTALS                          | P/o nr: N/A<br>(client to BV)           |
| Manufacturer: DOOSAN                               | P/o nr: N/A<br>(client to Manufacturer) |

| SUPPLY / SUBJECT OF INSPECTION                           | SN / TAG Nr | Owner ID No.: | QTY |
|----------------------------------------------------------|-------------|---------------|-----|
| VISUAL EXAMINATION AND FUNCTIONAL TEST OF AIR COMPRESSOR | CCGE435063  | SAC-435-054   | 1   |

DOCUMENTS OF REFERENCE : See continuation sheet for additional documents: ☐ Yes ☐ No

| Title                              | Reference n° | Rev. | Approved by | Date |
|------------------------------------|--------------|------|-------------|------|
| ORIGINAL DECLARATION OF CONFORMITY | -            | -    | -           | -    |

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>INSPECTIONS :</b><br><u>Inspection place &amp; Date or Period:</u><br><br>DAMMAM YARD<br><br>SEP 06, 2022<br><br><u>Stage of inspection :</u><br><input type="checkbox"/> Before manufacturing<br><input type="checkbox"/> During manufacturing<br><input checked="" type="checkbox"/> Final<br><input type="checkbox"/> Packing<br><br><u>Type of inspection:</u><br><input type="checkbox"/> Pre-inspection meeting<br><input type="checkbox"/> Document and QC record review<br><input checked="" type="checkbox"/> Visual examination, checks<br><input type="checkbox"/> Witnessing tests<br><input type="checkbox"/> Manufacturing progress status<br><input type="checkbox"/> Vendor assessment<br><input checked="" type="checkbox"/> Final inspection<br><input type="checkbox"/> Packing<br>(for details see continuation sheet)<br><u>Stamping :</u><br><input checked="" type="checkbox"/> No <input type="checkbox"/> <input type="checkbox"/> | <b>Results of inspection :</b> <input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> Unsatisfactory<br><br><u>Non Conformities Reports (NCR):</u><br>o NCR's issued during reported period : N/A<br><br>o List of outstanding NCR's : N/A<br><br><u>Main Conclusions &amp; Remarks:</u> (for details see continuation sheet)<br><br>Visual inspection and Function test was done for AIR COMPRESSOR and found satisfactory at the time of Inspection.<br><br>Valid Sticker Number : 01-34283<br><u>Next visit scheduled:</u> SEP 05 ,2023<br><br> |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|


☐ Interim  
☒ Final

## INSPECTION REPORT

NO. R109220906.05

BV Job nr: KHO.INI.22.SA.

Description of the inspections carried out:**1. Introduction:**

The undersigned surveyor to Bureau Veritas acting within the scope of work along with the General condition which Regulate the intervention of the society IVS-Lifting/B&F Department at the Request of SUDHIR RENTALS on the purpose of Third Party Inspection .

**2. Scope of Inspection :**

a. Visual Inspection &amp; Functional Test of AIR COMPRESSOR

**1- General Data**

|                |                |
|----------------|----------------|
| Equipment Type | AIR COMPRESSOR |
| Manufacturer   | DOOSAN         |
| Serial No.     | CCGE435063     |
| Owner ID No    | SAC-435-054    |
| Model:         | MHP435         |
| Rating         | 435 CFM        |

**2- Inspection and Test Results**

| Acceptance criteria                                                                                      | Result | Remarks               |
|----------------------------------------------------------------------------------------------------------|--------|-----------------------|
| 1. Document review (Original Declaration of Conformity)                                                  | Pass   | Available             |
| 2. Visual inspection of Unit, wear, damage, loose connection /components, corrosion.                     | Pass   | Found good condition. |
| 3. Electrical, (conduct general inspection of wiring and connection cable termination, corrosion, damage | Pass   | Found good condition. |

**➤ Conclusion:**

The AIR COMPRESSOR found in good condition at the time of Inspection.

Inspected by:

**Mohamed Omara**  
LIFTING EQUIPMENT INSPECTOR

Checked by:

OPERATION TEAM LEADER



Issued at Al Khobar office on SEP 06, 2022