


☐ Interim  
☒ Final

## INSPECTION REPORT

NO. R109220912.04

BV Job nr: KHO.INI.22.SA.

PROJECT: Third Party Inspection for AIR COMPRESSOR

Ref: KHO.INI.22.SA.

BV Client: SUDHIR RENTALS

P/o nr: N/A

(client to BV)

Manufacturer: DOOSAN

P/o nr: N/A

(client to Manufacturer)

| SUPPLY / SUBJECT OF INSPECTION                           | SN / TAG Nr | Owner ID No.: | QTY |
|----------------------------------------------------------|-------------|---------------|-----|
| VISUAL EXAMINATION AND FUNCTIONAL TEST OF AIR COMPRESSOR | CCFE435060  | SAC-435-059   | 1   |

DOCUMENTS OF REFERENCE : See continuation sheet for additional documents: ☐ Yes ☐ No

| Title                              | Reference n° | Rev. | Approved by | Date |
|------------------------------------|--------------|------|-------------|------|
| ORIGINAL DECLARATION OF CONFORMITY | -            | -    | -           | -    |

## INSPECTIONS :

Inspection place & Date or Period:

DAMMAM YARD

SEP 12, 2022

Stage of inspection :

- ☐ Before manufacturing  
☐ During manufacturing  
☒ Final  
☐ Packing

Type of inspection:

- ☐ Pre-inspection meeting  
☐ Document and QC record review  
☒ Visual examination, checks  
☐ Witnessing tests  
☐ Manufacturing progress status  
☐ Vendor assessment  
☒ Final inspection  
☐ Packing

(for details see continuation sheet)

Stamping:☒ No☐☐Results of inspection : ☒ Satisfactory ☐ UnsatisfactoryNon Conformities Reports (NCR):

o NCR's issued during reported period : N/A

o List of outstanding NCR's : N/A

Main Conclusions & Remarks: (for details see continuation sheet)

Visual inspection and Function test was done for AIR COMPRESSOR and found satisfactory at the time of Inspection.

Valid Sticker Number : 01-34294

Next visit scheduled: MARCH 11 ,2023

☐ Interim  
☒ Final**INSPECTION REPORT**

NO. R109220912.04

BV Job nr: KHO.INI.22.SA.

**Description of the inspections carried out:****1. Introduction:**

The undersigned surveyor to Bureau Veritas acting within the scope of work along with the General condition which Regulate the intervention of the society IVS-Lifting/B&F Department at the Request of SUDHIR RENTALS on the purpose of Third Party Inspection .

**2. Scope of Inspection :**

a. Visual Inspection &amp; Functional Test of AIR COMPRESSOR

**1- General Data**

|                |                |
|----------------|----------------|
| Equipment Type | AIR COMPRESSOR |
| Manufacturer   | DOOSAN         |
| Serial No.     | CCFE435060     |
| Owner ID No    | SAC-435-059    |
| Model:         | MHP435         |
| Rating         | 435 CFM        |

**2- Inspection and Test Results**

| Acceptance criteria                                                                                     | Result | Remarks               |
|---------------------------------------------------------------------------------------------------------|--------|-----------------------|
| 1. Document review (Original Declaration of Conformity)                                                 | Pass   | Available             |
| 2. Visual inspection of Unit, wear, damage, loose connection /components, corrosion.                    | Pass   | Found good condition. |
| 3. Electrical,(conduct general inspection of wiring and connection cable termination, corrosion, damage | Pass   | Found good condition. |

**➤ Conclusion:**

The AIR COMPRESSOR found in good condition at the time of Inspection.

Inspected by:

**Mohamed Omara**  
SENIOR LIFTING INSPECTOR

Checked by:

OPERATION TEAM LEADER

Issued at Al Khobar office on SEP 13, 2022

