



شركة مساندة الإعمار للفحص Emaar Support Inspection Co.

6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817

Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444

Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

CERTIFICATE OF THOROUGH EXAMINATION OF ELECTRIC POWER EQUIPMENTS

Date of thorough examination : 21-06-2026		Date of issue : 21-06-2026		Report No. : ESICO-LFT-R26-9471	
Name & Address of employer		Location		Sticker	
SUDHIR EQUIPMENT RENTALS		AL HASSA 7 SITE		11123	
				Standards	
				SASO EN 1012-1	
Equipment Identification No	Equipment Description		Safe Working Load(s)	Date of Manufacture	Manufacturer Name
SAC-250-198 OR VEPL/2023-24/495	AIR COMPRESSOR MODEL: XAS 250-100 MOTOR SPEED: 2300 RPM MOTOR POWER: 80 HP MASS: 1400 KG		Working Pressure: 7 bar/100 psi	FEB-2024	ATLAS COPCO
Is this the first examination after installaton or assembly at a new site or location? Yes ☐ - ☐ No ☒			Was the examination carried out within an interval of? - 12 Months		
If the answer to the above question is YES, has the equipment been installed correctly? Yes ☐ - ☐ No ☐			In accordance with an examination scheme? Yes ☒ No ☐ - ☐		
			After the occurence of exceptional circumstances? Yes ☐ - ☐ No ☒		
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE					
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?					No
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)				Yes by : NONE	
Particulars of any repair, renewal or alteration required to remedy the defect identified above : NONE					
Particulars of any tests carried out as part of the examination (if none state NONE) : NONE					
Observation/additional comments relative to this thorough examination : NO DEFECT FOUND AT THE TIME OF INSPECTION.					



For confirmation scan QR code
search with report number : **ESICO-LFT-R26-9471**



☒ Safe to operate

Next Inspection : 20-06-2027

Inspected by : ANSON

