

OWNERSHIP CERTIFICATE

To Whom It May Concern

This is to certify that the following equipment listed below is the sole property of Sudhir Equipment Rental Company:

Equipment	AWP
Brand / Make	Genie
Asset ID	S40SG-1175
Model Number	SX-125 XC
Serial Number	SX125D-2833
Working Height	40 Meter
Type	Diesel Telescopic Boom
Manufacturing Year	2024

This certification is issued to confirm the ownership status of the aforementioned equipment. Sudhir Equipment Rental Company holds full legal ownership rights over the listed equipment and retains all associated benefits and responsibilities. Should there be any queries or requests for verification regarding the ownership of the mentioned equipment, please do not hesitate to contact us at : Info@sudhirrentals.com

Sincerely,

Ajay Koul
General Manager
Sudhir Equipment Rental Company





Certificate of Insurance

Policy Holder Name
Policy Number
Original Policy Period

Sudhir Equipment Rental Company
5/EP/30425/0/0
05/04/2026 to 04/04/2027

اسم حامل الوثيقة
رقم الوثيقة
فترة الوثيقة الأصلية

Gulf Insurance Group certifies that above client is holding Contractor's Plant & Machinery Insurance Policy for the below mentioned Equipment in accordance with the above mentioned Insurance Policy:

تشهد مجموعة الخليج للتأمين بأن العميل المذكور أعلاه يحمل وثيقة تأمين على معدات والآلات المقاولين للمعدة المذكورة أدناه، وذلك وفقا لشروط وثيقة التأمين المذكورة أعلاه:

Asset ID : S40SG-1175
Brand : Genie
Type : SX-125 XC
Model : AWPS
Manufacturing Year : 2024
Equipment Serial Number : SX125D-2833
Insurance Effective Date : 05/04/2026

معرف الأصل
العلامة التجارية
النوع
الطراز
سنة الصنع
الرقم التسلسلي للمعدة
تاريخ سريان التأمين

This Certificate has been issued upon Insureds request as per all terms and conditions, exclusions, warranties mentioned in the policy.

تم اصدار هذه الشهادة بناء على طلب المؤمن له وذلك حسب الشروط والاستثناءات والاشتراطات المذكورة في الوثيقة

Al Khobar : 01st April 2026

Signature of Insurer's Authorized Representative



PUBLIC

Gulf Insurance Group

A Saudi joint stock company | Paid-up capital 500 Million Saudi Riyals
Licensed by No (TMN/25/20101) | Commercial Registration No.1010271203
3528 King Abdullah Bin Abdulaziz Road, Al Nuzha District
Unit No. 25 | Riyadh 12471 - 6378
Toll free 8001160020 | Website www.gig.sa
Regulated and Supervised by The Saudi Central Bank

مجموعة الخليج للتأمين

شركة مساهمة سعودية | رأس المال 500,000,000 ريال سعودي
مرخص لها برقم ترخيص (ت م ن/25/20101) | سجل تجاري رقم 1010271203
3528 طريق الملك عبدالله بن عبدالعزيز، حي النزهة
رقم الوحدة 25 | الرياض 12471 - 6378
www.gig.sa الرقم المجاني 8001160020 | الموقع الإلكتروني
خاضعة لرقابة وإشراف البنك المركزي السعودي



REPORT OF A THOROUGH EXAMINATION

Issue Date: 19-May-2026

Certificate Number: ECI/SA/C-01751/26 Rev. No: 02	Report Number: 132380	Sticker Number: 109691
Date of Thorough Examination: 18-May-2026	Date of Expiration: 17-Nov-2026	S.O.#: 239 Ref.#: N/A

Client: SUDHIR EQUIPMENT RENTAL COMPANY	Address of Premises at Which the Examination Was Made: SABIC, JUBAIL
---	--

Description and Identification of the Equipment:	Load Test Detail	Safe Working Load(s)	Applied Load(s)
Equipment / Type : MOBILE ELEVATING WORK PLATFORM / BOOM SUPPORTED - MANLIFT Location of the Equipment : SABIC, JUBAIL Equipment ID No : S40SG-1175 Equipment Serial No : SX125D-2833 Model : SX-125XL Manufacturer / Date of Manufacture : GENIE / 2024 Applied Standard : SASO-ISO-18893 : 2014 & ANSI/SAIA A92.5 : 2006(2014)	N/A	Platform Capacity: 300 kg	N/A

Examination after installation / In-Services		Was the Examination carried out Within an interval of					
☐ Initial ☒ Periodic Inspection ☐ Re-Inspection after Major Repair / Modification Or Overhaul		☐ 3 Months ☒ 6 Months ☐ 12 Months ☐ After the exceptional circumstances					
Additional Information about the equipment and Information / Description of the Parts / attachments with the equipment.							
Description of the Load Test : N/A							
Pre Load Test NDT done by : N/A		% of Load Applied : N/A		Post Load Test NDT done by : N/A			
Expiration of Load Test : N/A							
Result				PASS	☒	FAIL	
Is the above a defect which is of immediate danger to persons?				YES		NO	☒
Is the above a defect which is not yet but could become a danger to persons?				YES by :		NO	☒
Particulars of any repair, renewal or alteration required to remedy the defect identified above: N/A							
Is this equipment safe to operate?				YES	☒	NO	

Note: We thus attest that the aforementioned equipment has undergone a thorough Visual Inspection and /or Functional Test conducted by a qualified inspector in accordance with Engineering Corner for Inspection (E.C.I.) procedure / local / international standards.

Liability: The client or this assignee or supervisor in interest agrees to identify and hold harmless **Engineering corner for inspection Co.Ltd.** from and against any all claims, demands, lawsuits or actions for damages including legal fees to persons and/or property tangible, intangible or otherwise which may be against, **Engineering corner for inspection Co.Ltd.** incidental to, arising out of or in connection with the work to be done, services to be performed or material to be furnished hereunder except for those claims caused solely and completely by the negligence of **Engineering corner for inspection Co.Ltd.** its directors, others, employees or sub-contractors.

Inspected by: A.Muhammad Raseen Signature:	Approved & Reviewed By: ALVARO 	QR Code:
---	--	--------------

	Engineering Corner for Inspection Company Limited INSPECTION CHECKLIST Mobile Elevating Work Platform	Doc. No.	ECIR - LFT - 109
		Rev. No.	02
		Rev. Date	17-FEB-2026
		Page No.	2 of 4

Issue Number : 02 & Issue Date : 03-FEB-2020

Equipment Owner	SUDHIR EQUIPMENT RENTAL COMPANY /	Report No. & Date	132380 18-May-2026
Manufacturer / Year	GENIE / 2024	Location	SABIC, JUBAIL
Type / Model	MOBILE ELEVATING WORK PLATFORM / BOOM SUPPORTED - MANLIFT / SX-125XL	Equipment ID. No.	S40SG-1175
Inspection Date	18-May-2026	Equipment Sr. No.	SX125D-2833
Inspector Name	A.Muhammad Raseen	Capacity / SWL	Platform Capcity: 300 kg
Standard	SASO-ISO-18893:2014	Expiration Date	17-Nov-2026

Item No	ITEM NAME	PASS	FAIL	N/A	Item No	ITEM NAME	PASS	FAIL	N/A
DOCUMENTATION & RECORDS					5.1	Wiring harness: No frayed wires, loose connections, or chafing.	☒		
1.1	Previous Inspection report	☒			5.2	Battery: Terminals clean and tight; fluid level correct; no corrosion.	☒		
1.2	Operator's manual (handbook) is present and legible.	☒			5.3	Limit switches and sensors: Present, securely mounted, and appear functional.	☒		
1.3	Maintenance and inspection records are available and up-to-date.	☒			POWER UNIT & DRIVE				
1.4	All decals, warnings, and control markings are in place and legible.	☒			6.1	Engine/Motor: Fluids correct (oil, coolant, fuel).	☒		
1.5	Manufacturer's safety bulletins have been checked and complied with (if applicable).	☒			6.2	Fuel system: No leaks.	☒		
STRUCTURAL INTEGRITY					6.3	Brakes: Function properly (including parking brake).	☒		
2.1	Chassis and frame: No visible cracks, deformation, or damage.	☒			6.4	Steering: Operates smoothly with no excessive play.	☒		
2.2	Extending structure (boom, mast, scissors): No cracks, distortion, or weld damage.	☒			6.5	Wheels and tires: Proper inflation (if pneumatic), no damage.	☒		
2.3	Work platform floor: Clean, no holes, anti-skid surface intact.	☒			6.6	Wheel nuts/fasteners: Torqued properly and present.	☒		
2.4	Guardrail system: Top rail, mid-rail, and toe boards are secure and undamaged.	☒			FUNCTIONAL TEST				
2.5	Entrance gate / chain: Self-closing and self-latching (if so equipped).	☒			7.1	Ground Controls: All functions operate smoothly (lift, lower, extend, rotate).	☒		
2.6	Anchor points (for fall arrest): Present, undamaged, and clearly marked.	☒			7.2	Platform Controls: All functions operate smoothly from platform.	☒		
2.7	Fasteners, pins, and shafts: Secured, no visible wear or distortion.	☒			7.3	Emergency Stop: Functions from both ground and platform.	☒		
STABILIZATION & SUPPORT					7.4	Auxiliary/Manual Descent: Operates correctly and lowers platform.	☒		
3.1	Stabilizers/Outriggers: Deploy smoothly, no visible damage or leaks.	☒			7.5	Drive and steer functions: Operate correctly (test at low and high speed, if applicable).	☒		
3.2	Pad/Foot plates: Present, not worn out, and swivel freely.	☒			7.6	Tilt alarm/indicator: Functions correctly (simulate slope if safe).	☒		
3.3	Locking devices: All pins, latches, or locks function and secure properly.	☒			7.7	Load sensing system (if equipped): No fault codes visible.	☒		
3.4	Oscillating axle: Locking mechanism functions (if applicable).	☒			7.8	Horn and Alarms: Audible and functioning.	☒		
MECHANICAL & HYDRAULIC SYSTEMS					7.9	Pothole protection system (Scissor lifts): Deploys automatically when elevated.	☒		
4.1	Hydraulic hoses and fittings: No leaks, abrasion, kinks, or bubble/swelling.	☒			7.10	Platform overload indicator (if equipped): Functions correctly.	☒		
4.2	Hydraulic oil level: Correct (check sight glass/dipstick).	☒			SPECIFIC SAFETY DEVICES				
4.3	Cylinders: No visible damage, leaks, or rod scoring.	☒			8.1	Lanyard attachment points: Secure and undamaged.	☒		
4.4	Lubrication: All pivot points and moving parts are greased/lubricated.	☒			8.2	Motion alarms / beacon lights: Working (if applicable).	☒		
4.5	Cables and wire ropes: No fraying, broken strands, or corrosion; properly tensioned.	☒			8.3	Insulating boom (if applicable): Inspected per IEC/TS 61813.	☒		
4.6	Chains: Properly tensioned, lubricated, and no visible wear/stretch.	☒			8.4	Communication system (platform to ground): Working (if required).	☒		
ELECTRICAL SYSTEM									

Overall Comments

Inspected By : A.Muhammad Raseen	Customer Representative : ARIF
----------------------------------	--------------------------------



شركة ركن الهندسة للفحص والمعاينة المحدودة

ENGINEERING CORNER FOR INSPECTION CO. LTD.

Certificate Number: ECI/SA/C-01751/26





شركة ركن الهندسة للفحص والمعاينة المحدودة
ENGINEERING CORNER FOR INSPECTION CO. LTD.



ENGINEERING CORNER FOR
INSPECTION CO. LTD. (ECI)



ECI. 109691

Capacity : Platform Capacity: 300 kg

Equipment No. : S40SG-1175

Serial No. : SX125D-2833

Inspected Date : 18-May-2026

Next Inspection : 17-Nov-2026

Inspector : A.Muhammad Raseen

P.O.Box 235 Rastanura 31941 Kingdom of Saudi Arabia

Tel.: (013) 667-6999 / 667-6895 Fax #:(013) 667-6894

E-mail Address:eci@eccgroupksa.com



ENGINEERING CORNER FOR
INSPECTION COMPANY LTD.



ECI.109691

Capacity : Platform Capacity : 300 kg

Equipment No. : S40SG1-1175

Serial No. : SX125D-2833

Inspected Date : 18 - May - 2026

Next Inspection : 17 - Nov - 2026

Inspector : A. Raseen

P.O.Box 235 Rastanura 31941 Kingdom of Saudi Arabia
Tel.: (013) 667-6999 / 667-6895 Fax #:(013) 667-6894
E-mail Address: eci@eccgroupksa.com