



BUREAU
VERITAS

BV No. 236864

LIFTING EQUIPMENT INSPECTION REPORT	Area DAMMAN	Inspection Date SEP 08, 2023		Inspection Time 10:30	Previous Sticker No. IWM Issued By
Department / contractor SUDHJL	Equipment Number SEIGAD-807	Equipment Location DMMYORD		Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-21-9524
Manufacturer DINGLI	Model BAIGNE	Capacity 230kg	Type NEW	Equipment Serial Number E0333	Sticker Expiration Date MARCH 07, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards.
Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
4	Initial Inspection and function test for	
	Beam supports elevating work not done	
	AS PER S. ARAMCO 617.034 1015 92.5	
	"Pass"	

RECEIVER NAME: ARJ SIGNATURE: [Signature] INSPECTOR NAME: M. Olan
BADGE#: TELEPHONE NO.: TELEPHONE NO.: 80019606