



BUREAU
VERITAS

BV No. 236859

LIFTING EQUIPMENT INSPECTION REPORT	Area DAMPWAD	Inspection Date SEP 07, 2023		Inspection Time 10:30	Previous Sticker No. 34714 Issued By
Department / contractor SUDHAR	Equipment Number SE16AD-811	Equipment Location DAMPWAD		Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-21-9519
Manufacturer DINBLT	Model BA16NE	Capacity 230KG	Type MFWP	Equipment Serial Number E0334	Sticker Expiration Date MARCH 06, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
	* Initial inspection and function test for	
	boom support and clevis were not done	
	As per AS S-ORAM 6 G 7.0 3. MSJ 2.5	
	" Pass "	

RECEIVER NAME: ARSH	SIGNATURE: [Signature]	INSPECTOR NAME: M. M. M.
BADGE#:	TELEPHONE NO.:	TELEPHONE NO.: 800 19106