



Previous Sticker
No. Indu Issued By

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker No. <u>Indm</u> Issued By
	<u>DAMMAN</u>	<u>SEP 08, 2023</u>		<u>17:00</u>	
Department / contractor <u>SUDHAR</u>	Equipment Number <u>S DINESH - 814</u>	Equipment Location <u>DMMYARD</u>		Equipment Result ☒ Pass ☐ Fail	New Sticker No. <u>BV-21-9527</u>
Manufacturer <u>DINGLI</u>	Model <u>JCPT1412 AC</u>	Capacity <u>700LBS</u>	Type <u>MEWP</u>	Equipment Serial Number <u>C01393</u>	Sticker Expiration Date <u>MARCH 07, 2024</u>

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
4	Initial inspection was conducted for self prepared closely with MS team. As per as S. Sharma G703, KMS92.G. "Raj"	

RECEIVER NAME: ARIF SIGNATURE: [Signature] INSPECTOR NAME: M. Othman
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 80019606