



Previous Sticker
No. 32174 Issued By

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker
	Dammam	SEP 25, 2023		9:00	No. 32174 Issued By
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
Suofu	SDME5L-827	Dammam		☒ Pass ☐ Fail	BV-21-9567
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
DINGLI	SCPT1412AC	300 LBS	MEWP	B00471	MARCH 24, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

[illegible]

RECEIVER NAME: ARIF SIGNATURE: [Signature] INSPECTOR NAME: M. o Mmz
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 80019106