



BV No. 237181

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker
	Dormitory	Oct 04, 2023		12:00	No. 24744 Issued By
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
Suohs	SD16ESL-844	DMH YARD		☒ Pass ☐ Fail	B0-21-9589
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
DING LI	JCPT1614AC	700LBS	MEWP	C01387	APRIL 03, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

[illegible]

RECEIVER NAME: ARJ SIGNATURE: [Signature] INSPECTOR NAME: M. O'Neil
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 800 19108