



BUREAU  
VERITAS

BV No. 237207

|                                                |                               |                                 |                                                                                            |                                           |
|------------------------------------------------|-------------------------------|---------------------------------|--------------------------------------------------------------------------------------------|-------------------------------------------|
| <b>LIFTING EQUIPMENT<br/>INSPECTION REPORT</b> | Area<br>DAMMAN                | Inspection Date<br>OCT 12, 2023 | Inspection Time<br>8:30                                                                    | Previous Sticker<br>No. Initial Issued By |
| Department / contractor<br>SUDAJR              | Equipment Number<br>SH05G-854 | Equipment Location<br>DMMYARD   | Equipment Result<br><input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail | New Sticker No.<br>B0-21-9716             |
| Manufacturer<br>GENIE                          | Model<br>SX-125XC             | Capacity<br>227KG               | Type<br>NEW                                                                                | Equipment Serial Number<br>SX12SD-904     |
|                                                |                               |                                 |                                                                                            | Sticker Expiration Date<br>APRIL 11, 2024 |

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards.  
Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

| No. | DEFICIENCIES                            | CORRECTIVE ACTION TAKEN |
|-----|-----------------------------------------|-------------------------|
| X   | Initial inspection was further test for |                         |
|     | Boom supported elevating work platform  |                         |
|     | As per the schedule (17-03-2023) 2.3    |                         |
|     | "PASS"                                  |                         |
|     | ✓                                       |                         |
|     |                                         |                         |
|     |                                         |                         |
|     |                                         |                         |
|     |                                         |                         |
|     |                                         |                         |
|     |                                         |                         |
|     |                                         |                         |

RECEIVER NAME: ARTJ SIGNATURE: [Signature] INSPECTOR NAME: M. M. M. M.  
BADGE#: TELEPHONE NO.: TELEPHONE NO.: 801966