



**BV No.** 237196

|                                                |                               |                                 |              |                                                                                            |                                             |
|------------------------------------------------|-------------------------------|---------------------------------|--------------|--------------------------------------------------------------------------------------------|---------------------------------------------|
| <b>LIFTING EQUIPMENT<br/>INSPECTION REPORT</b> | Area<br>Dammam                | Inspection Date<br>Oct 09, 2023 |              | Inspection Time<br>14:30                                                                   | Previous Sticker<br>No. 2017-1234 Issued By |
| Department / contractor<br>SUDHAR              | Equipment Number<br>SY056-855 | Equipment Location<br>DMM YARD  |              | Equipment Result<br><input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail | New Sticker No.<br>BU-21-9705               |
| Manufacturer<br>GENIE                          | Model<br>SX125Xc              | Capacity<br>227kg               | Type<br>MEWP | Equipment Serial Number<br>SX1250-831                                                      | Sticker Expiration Date<br>APR 10, 2024     |

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

| No. | DEFICIENCIES                                                                                                                        | CORRECTIVE ACTION TAKEN |
|-----|-------------------------------------------------------------------------------------------------------------------------------------|-------------------------|
| *   | Initial inspection and Function test for<br>Boom Supported Elevating work platform<br>AS per AS 2549-2006 G5710 ZC, WMSG 925<br>RSS |                         |
|     |                                                                                                                                     |                         |
|     |                                                                                                                                     |                         |
|     |                                                                                                                                     |                         |
|     |                                                                                                                                     |                         |
|     |                                                                                                                                     |                         |
|     |                                                                                                                                     |                         |
|     |                                                                                                                                     |                         |
|     |                                                                                                                                     |                         |
|     |                                                                                                                                     |                         |
|     |                                                                                                                                     |                         |

RECEIVER NAME: ARJ SIGNATURE: [Signature] INSPECTOR NAME: M. C. Morris

BADGE#: TELEPHONE NO.: TELEPHONE NO.: 80219106