



BV No. 237197

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker
	DMMOM	OCT 09, 2023		15:30	No. 21-9706 Issued By
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
SUTOR	S4056-856	DMM YARD		☒ Pass ☐ Fail	Bv-21-9706
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
GENIE	SX125XC	227KG	MEWP	SX1250-903	APRIL 08, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
4	Initial inspection was performed for Best supported clearing work per LHM AJ Dennis S. Orange 6/17/03, AMS 92.5 P.O.J.S.	

RECEIVER NAME: ARL SIGNATURE: [Signature] INSPECTOR NAME: M. M. M. M.
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 800/9/0