



LIFTING EQUIPMENT INSPECTION REPORT	Area Dammam	Inspection Date Nov 02, 2023		Inspection Time 9:00	Previous Sticker No. 2 with Issued By
Department / contractor SUDAIR	Equipment Number S4056-867	Equipment Location DMR 1020		Equipment Result ☒ Pass ☐ Fail	New Sticker No. BU-23-0008
Manufacturer GENIE	Model SX125-XC	Capacity 22700	Type MEWP	Equipment Serial Number SX125D-907	Sticker Expiration Date MAY 01, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
*	Initial inspection and function test per Boom Support Elevating work plat form For Boom Support elevating work plat form As Per AS SOURCE G-70 Jo. NSI92.5 Ross	

RECEIVER NAME: ARTJ SIGNATURE: [Signature] INSPECTOR NAME: M. A. Mills
BADGE#: TELEPHONE NO.: TELEPHONE NO.: 800 19 / 06