



LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker
	DMM MRM	OCT 31, 2023		10:30	No. 217124 Issued By
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
SCHL	S4056-868	DMM MRM		☒ Pass ☐ Fail	BV-21974
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
GEMIE	SX125-XC	227kg	MC up	SX125D-1281	APR 30, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
4	Initial inspection and function test for Room Separators (ceiling work Met here. AB Per as S. Room Co GS 703, and 92.5 Pass	

RECEIVER NAME: AKS SIGNATURE: [Signature] INSPECTOR NAME: M. C. M. G.
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 80029106