



BUREAU
VERITAS

BV No. 236911

LIFTING EQUIPMENT INSPECTION REPORT	Area Dammam	Inspection Date Nov 11, 2023	Inspection Time 11:00	Previous Sticker No. 32124 Issued By
Department / contractor SUDHJR	Equipment Number S285J-871	Equipment Location Dammam	Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-23-6019
Manufacturer JLG	Model 8605T	Capacity 5000LBS	Type MEWP	Equipment Serial Number 0300205979
				Sticker Expiration Date MAY 10, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards
Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Initial inspection and further test for	
	Boom Support and Clevis work not done	
	AS Per AS S. ORANGE 6370.30. AMS 392.5	
	Reqs	

RECEIVER NAME: **ARTS** SIGNATURE: **[Signature]** INSPECTOR NAME: **M. M. M.**
BADGE#: TELEPHONE NO.: **80019106**