



BV No. 239039

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker
	DAMMAN	JAN 01, 2024		18:00	No. 3212 Issued By
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
SUDAIR	S22ST-902	DMVARD		☒ Pass ☐ Fail	BN-23-0097
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
JLG	660ST	2500KG	MEWP	B300014415	JUNE 30, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Initial Inspection and Function test for Beam Supported Elevating work platform. As per AS 5686 G27.03-ANSI 92.5	
	"Pass"	

RECEIVER NAME: APR SIGNATURE: [Signature] INSPECTOR NAME: M. [Signature]
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 82219106