



BUREAU
VERITAS

BV No. 239049

LIFTING EQUIPMENT INSPECTION REPORT	Area DAMMAM	Inspection Date JAN 03 2024		Inspection Time 16:00	Previous Sticker No. Initial Issued By
Department / contractor SUDHAR	Equipment Number S225J-911	Equipment Location DAMMAM		Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-23-0207
Manufacturer JLG	Model 6605J	Capacity 5000LBS	Type MFWD	Equipment Serial Number B300014182	Sticker Expiration Date JULY 02, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Initial inspection and function test for	
	Beam supported elevating work platform	
	AS PER SAUDI ARAMCO GI 7.03, AMST 9.2.5	
	PASS	

RECEIVER NAME: ARTI SIGNATURE: [Signature] INSPECTOR NAME: M. Al-Muray
BADGE#: TELEPHONE NO.: TELEPHONE NO.: 8019106