

BV No. 239080

LIFTING EQUIPMENT INSPECTION REPORT	Area Dammam	Inspection Date JAN 16, 2024		Inspection Time 9:00	Previous Sticker No. 21700 Issued By
	Department / contractor SUDAR	Equipment Number 52855-927	Equipment Location DMMAMD	Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-23-0835
Manufacturer JLG	Model 86055	Capacity 5000LBS	Type MEWP	Equipment Serial Number B300022761	Sticker Expiration Date JULY 15, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
x	Initial Inspection and Function Test for Beam supported elevating work platform. As per as SABC 607.030, AWS 925 Pass	

RECEIVER NAME: ART SIGNATURE: [Signature] INSPECTOR NAME: M. J. [Signature]
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 800 19 106