



Previous Sticker
No. 24712 Issued By

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker
	DK MMSH	JAN 16, 2024		13:00	No. E-112 Issued By
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
SUDAJR	S 285J-929	DMH YARD		☒ Pass ☐ Fail	BU-23-0837
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
JLG	860SS	5000LB	MEWP	B300022557	JULY 15, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's ,ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

[illegible]

RECEIVER NAME: ABOV SIGNATURE: [Signature] INSPECTOR NAME: M. M. M.
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 8009106