

# CERTIFICATE OF THOROUGH EXAMINATION

## SCISSOR LIFT

**CERTIFICATE / REPORT NO : CRT-137843**

STICKER NO : 110949

**JOB NO : WO-37713**

|                                                                             |                                      |                                             |                                    |
|-----------------------------------------------------------------------------|--------------------------------------|---------------------------------------------|------------------------------------|
| EQUIPMENT OWNER :<br>SUDHIR RENTALS                                         |                                      | TYPE OF INSPECTION :<br>INITIAL INSPECTION. |                                    |
| LOCATION:<br>RIYADH                                                         | DATE OF INSPECTION :<br>28-Sep-2024  | Frequency<br>6 month                        | Next Inspection Due<br>27-Mar-2025 |
| EQUIPMENT DESCRIPTION :<br>BATTERY OPERATED HYDRAULIC POWERED SCISSOR LIFT. |                                      |                                             |                                    |
| MANUFACTURER :<br>GENIE                                                     | MODEL/ TYPE OF EQUIPMENT :<br>GS3246 | MANUFACTURED YEAR :<br>2024                 |                                    |
| SERIAL NO :<br>GS4615D-1957                                                 | OWNER ID / PLATE NO :<br>SG12ESL-940 | WORK PROCEDURE NO :<br>SA-WP-04             |                                    |
| REFERENCE STANDARDS :<br>BS EN 280-1:2022, SASO GSO EN 280                  | DATE OF PREVIOUS INSPECTION :        | PREVIOUS INSPECTION DETAILS:<br>NA          |                                    |

|                                                                                                                                                                                                                                                                                    |                                  |                                         |                               |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|-----------------------------------------|-------------------------------|
| <b>MAXIMUM PLATFORM HEIGHT :</b><br>11.78 M                                                                                                                                                                                                                                        |                                  | <b>MAXIMUM HORIZONTAL REACH :</b><br>NA |                               |
| <b>SOURCE OF POWER :</b><br>BATTERY POWERED                                                                                                                                                                                                                                        |                                  | <b>OUTRIGGER TYPE :</b><br>NA           |                               |
| <b>SAFE WORKING LOAD (SWL) :</b><br>318 KG                                                                                                                                                                                                                                         | <b>TEST LOAD APPLIED :</b><br>NO |                                         | <b>PERSONS ALLOWED :</b><br>2 |
| <b>WORK PLATFORM DIMENSIONS :</b><br>2.26 X 1.17 M                                                                                                                                                                                                                                 |                                  | <b>EXPLOSION PROOFING :</b><br>NA       |                               |
| <b>RESULT :</b><br>SATISFACTORY                                                                                                                                                                                                                                                    |                                  | <b>CHECKLIST NO :</b><br>56697          |                               |
| <b>REMARKS/RECOMMENDATION :</b><br>AT THE TIME OF INSPECTION THE SCISSOR LIFT WAS INSPECTED FOR ITS COMPLETE WORKING & FOUND IN GOOD CONDITION. EMERGENCY STOP, WHEELS, LIGHTS, HORN, ACCESS, STRUCTURE ETC WERE IN GOOD CONDITION AND HENCE FOUND SATISFACTORY FOR CONTINUED USE. |                                  |                                         |                               |

**Reviewed By : MOHAMED ANWAR DEEN**

Authorised Inspector : ZEESHAN KHALIL



*Zulma*

ملحوظة: تؤكد شهادة الفحص هذه أن المعدات التي تم فحصها تتوافق مع المتطلبات المحددة وفقاً لمعايير الفحص. مع ذلك، هذه الوثيقة لا تعتبر شهادة مطابقة لمنصة سابر.

**THIS CERTIFICATE BECOMES INVALID, IF ANY ALTERATION/REPAIR OR MODIFICATION IS MADE TO THE EQUIPMENT**

THE CONCERNED INSPECTOR OR REPRESENTATIVE HAS THOROUGHLY EXAMINED THE EQUIPMENT IN ACCORDANCE TO THE RELEVANT STANDARDS. EXAMINATION INDICATES THAT THE SAID EQUIPMENT HAS NO APPARENT DEFECTS OR DETERIORATION WHICH MAY PROVE DANGEROUS DURING NORMAL OPERATION. THE SAID EQUIPMENT IS FOUND TO BE SUBSTANTIALLY IN GOOD ORDER AND CONDITION. THERE IS REGULAR MAINTENANCE AND OPERATED BY CERTIFIED OPERATORS. THIS CERTIFICATE IS GRANTED SUBJECT TO THE CONDITION THAT IS AGREED AND UNDERSTOOD THAT STANDARD ARABIA INSPECTION CO. LTD.'S LIABILITY SHALL BE LIMITED TO THE ACTS OF ITS EMPLOYEES ON PREMISES OF SUBCONTRACTORS. UNDER NO CIRCUMSTANCES WHATSOEVER SHALL STANDARD ARABIA INSPECTION CO. LTD. BE LIABLE FOR ANY INJURY OR DAMAGE TO ANY PERSON OR OCCURRING AS A RESULT OF NEGLIGENT OPERATION OR ANY DEFECT IN MATERIALS, MACHINERY, EQUIPMENT OR SYSTEMS OTHER THAN DEFECTS ASCERTAINABLE DURING ROUTINE INSPECTION. WE HEREBY REPORT THAT THE ALL PARTICULARS IN THIS REPORT ARE CORRECT AT THE TIME OF TEST / INSPECTION & OPERATIONAL MAINTENANCE IS THE SOLE RESPONSIBILITY OF THE EQUIPMENT OWNER.

THIS CERTIFICATE IS GENERATED AND AUTHORIZED ELECTRONICALLY AND CAN BE CONSIDERED AS ORIGINAL. TO VERIFY THE AUTHENTICITY OF THIS CERTIFICATE, PLEASE SCAN THE QR CODE.