



BV No. 239084

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker No. <u>Int-100</u> Issued By
	<u>DAMMAM</u>	<u>JAN 17, 2024</u>		<u>13:00</u>	
Department / contractor <u>SUDAIR</u>	Equipment Number <u>S28AD-960</u>	Equipment Location <u>DMM KORO</u>		Equipment Result ☒ Pass ☐ Fail	New Sticker No. <u>BV-23-0843</u>
Manufacturer <u>DINGLI</u>	Model <u>BA28RT</u>	Capacity <u>250KG</u>	Type <u>MEWP</u>	Equipment Serial Number <u>R00097</u>	Sticker Expiration Date <u>JULY 16, 2024</u>

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

[illegible]