



LIFTING EQUIPMENT INSPECTION REPORT	Area Dammam	Inspection Date Feb 04, 2024		Inspection Time 11:00	Previous Sticker No. Initial Issued By
	Department / contractor Sudaja	Equipment Number S43SJP-972	Equipment Location Dammam	Equipment Result ☒ Pass ☐ Fail	New Sticker No. BU-23-0876
Manufacturer JLG	Model 1350SJP	Capacity 5000LBS	Type MEW	Equipment Serial Number 0300183075	Sticker Expiration Date Aug 03, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
	* Initial Inspection and function test for	
	Beam supported elevatory were not done	
	AS PERIODS S.A.RONG GET 7-03 MONTH 92.5	
	1 Pass	
		

RECEIVER NAME: prot SIGNATURE: [Signature] INSPECTOR NAME: M. Chama
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 8009106