



Previous Sticker
No. Ind 146 Issued By

LIFTING EQUIPMENT INSPECTION REPORT	Area DAMMM	Inspection Date JAN 29, 2024		Inspection Time 13:00	Previous Sticker No. 2nd Mtr Issued By
Department / contractor SUDAIR	Equipment Number 5435JP-974	Equipment Location DMM/KRIS		Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-23-0869
Manufacturer JLG	Model 13505JP	Capacity 5000BS	Type MEMP	Equipment Serial Number 0300203458	Sticker Expiration Date JULY 28, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's ,ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
x	Initial inspection and function test per Boom supported elevating work platform AS per AS S.A.R.M.C. GI 7.0 30.05.92.5 "Pass"	

RECEIVER NAME: A. P. S. K. SIGNATURE: [Signature] INSPECTOR NAME: [Signature]
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 80019106