




مؤسسة جبال هيمالايا للفحص

JABAL HEMALAYA FOR INSPECTIONS



Certificate of Thorough Visual and Functional Examination of Spider Boom lift (MEWP)

Certificate No: JHI-10364-26-C2

Date of Inspection: 07-09-2026

Name of the owner company:
SUDHIR EQUIPMENT RENTAL COMPANY

Location:
RIYADH-KSA

Equipment Details: MOBILE ELEVATING WORK PLATFORM – SPIDER BOOM LIFT (MEWP)

Type: DIESEL POWERED SPIDER BOOM LIFT

Reference Regulations:

Maker & Date of Manufacture:

SASO-ISO-18893:2014, BS EN 280-1:2022

JLG & 2024

Traffic Plate No:

Owner No.

Model No.

Chassis No. / Serial No.

N/A

S26SPJ-1367

X26JP

C170003988

Sticker No:

Max. Platform Height.

Max. Vertical Reach.

Platform Dimension.

020168

23.6m

26.0m

0.69x1.34m

Max. Rated Capacity: 230 Kg (2 Occupants + 70 kg Tools)

Description of Test:

VISUAL AND LOAD TEST @1.25 X MAX RATED CAPACITY WERE SATISFACTORY

Note: DURING OPERATION, FULL BODY HARNESS SHOULD BE WORN.

Date of Last Examination

Date of Next Examination

NA

06-03-2027

RECOMMENDATION / REMARKS

At the time of inspection, the equipment was found satisfactory. After Any Major Repair Proof Load Needs to be Conducted

IMAGES FOR SPIDER BOOM LIFT



*Certificate becomes invalid, if any alteration/major repair/modernization made on the Equipment in which case it must be re-examined and re-tested.

THIS IS TO CERTIFY THAT the Undersigned, a competent representative, did, attend to examine this equipment in accordance to the aforementioned standard to ascertain its safe working load and that the examination indicated that the said equipment has no indigenous injury or sighted deformation and the safe working load of the said equipment as either identified or test proof loaded is shown. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, implementation of our remarks & recommendations and qualified operators employed.

Authorized Name: ZEESHAN MAQSOOD

Surveyor's Name: MOHAMED AZARUDEEN

Authorized Signature:

Surveyor's Signature:

This certificate is granted subject to the condition that is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, express or implied, and Jabal Hemalaya For Inspections liability shall be limited to the acts or omissions of its employees, agents and subcontractors. Under no circumstances whatsoever shall Jabal Hemalaya For Inspections nor their Engineers be liable for any loss or damage to any person or property by reason of negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted standards and only those items actually inspected by Jabal Hemalaya For Inspections and which are covered by this certificate. Any person not a party to the contract pursuant to which this document is delivered may not assert claim against Jabal Hemalaya For Inspections for any liability arising out of errors or omissions which may be contained in said document and in connection with any activities for which it may provide. This certificate shall not be reproduced except in full without the approval of Jabal Hemalaya For Inspections.

Disclaimer: This certificate is issued subject to the observation made at the time of inspection. The company (Jabal Hemalaya) will not be held liable for any damage/losses associated to the equipment/material

Address: Est. Jabal Hemalaya for Inspections, Saudi Arabia, Riyadh. Po. 12628

CR No: 1010927177, Tel: 0112334900, Email: info@jhinspection.com, www.jhinspection.com

Annex to Certificate of Thorough Examination

Certificate No.: JHI-10364-26-C2

Date of Inspection: 07-09-2026

No.	DESCRIPTION	CONDITION (If Not Applicable, Explain Why ?)
1.	EQUIPMENT DOCUMENTS	SATISFACTORY
2.	IDENTIFICATION ON CONTROL LEVERS	SATISFACTORY
3.	REFLECTIVE TAPE AND MARKINGS	SATISFACTORY
4.	WORKING PLATFORM	SATISFACTORY
5.	ELECTRICAL SYSTEM	SATISFACTORY
6.	HYDRAULIC SYSTEM	SATISFACTORY
7.	NO. OF WHEEL BOLTS PROPERLY TORQUED WITH NO SIGN OF LOOSENING	NA (NO WHEELS AVILABLE)
8.	LOAD TEST: RESTRICTED MODE AT RATED CAPACITY AS PER MANUFACTURER'S SPECIFICATION.	NOT REQUIRES AS PER MANUFACTURE SPECIFICATION NO. X26JP
9.	LOAD TEST: UNRESTRICTED MODE AT RATED CAPACITY AS PER MANUFACTURER'S SPECIFICATION.	NOT REQUIRES AS PER MANUFACTURE SPECIFICATION NO. X26JP
10.	POWER UNIT CONTROL PANAL – UPPER	SATISFACTORY
11.	POWER UNIT CONTROL PANAL – LOWER	SATISFACTORY
12.	OVER LOAD WARNING	SATISFACTORY
13.	EMERGENCY DESCENT	SATISFACTORY
14.	BRAKES	SATISFACTORY
15.	BATTERY CONDITION	SATISFACTORY
16.	HORNS	SATISFACTORY
17.	FIRE EXTINGUISHER	SATISFACTORY
18.	OVER ALL BODY CONDITION	SATISFACTORY
19.	GUARD RAILS	SATISFACTORY
20.	MAINTENANCE RECORDS	SATISFACTORY

COMMENTS: At the time of inspection, the equipment was found satisfactory.

Surveyor's Name: **MOHAMED AZARUDEEN**



Surveyor's Signature:

M. Mohamed Azarudeen

Address: Est. Jabal Hemalaya for Inspections, Saudi Arabia, Riyadh. Po. 12628

CR No: 1010927177, Tel: 0112334900, Email: info@jhinspection.com, www.jhinspection.com