

Interim
Final

INSPECTION REPORT

NO. R109220130.2

BV Job nr: KHO.INI.22.SA.

PROJECT: Third Party Inspection for GENERATOR	Ref: KHO.INI.22.SA.
BV Client: Sudhir Rentals	P/o nr: N/A (client to BV)
Manufacturer: LEYLAND	P/o nr: N/A (client to Manufacturer)

SUPPLY / SUBJECT OF INSPECTION	SN / TAG Nr	Owner ID No.:	QTY
VISUAL EXAMINATION AND FUNCTIONAL TEST OF GENERATOR	VEPL/2017-18/0130	SG-246-160	1

DOCUMENTS OF REFERENCE : See continuation sheet for additional documents: Yes No

Title	Reference n°	Rev.	Approved by	Date
ORIGINAL DECLARATION OF CONFORMITY	-	-	-	-

INSPECTIONS :		Results of inspection : Satisfactory Unsatisfactory	
Inspection place & Date or Period: Sudhir Rental Warehouse, DAMMAM YARD JAN 30, 2022		Non Conformities Reports (NCR): ☐ NCR's issued during reported period : N/A ☐ List of outstanding NCR's : N/A	
Stage of inspection : Before manufacturing During manufacturing Final Packing		Main Conclusions & Remarks: (for details see continuation sheet) Visual inspection and Function test was done for Generator and found satisfactory at the time of Inspection.	
Type of inspection: Pre-inspection meeting Document and QC record review Visual examination, checks Witnessing tests Manufacturing progress status Vendor assessment Final inspection Packing (for details see continuation sheet)		Valid Sticker Number : 01-29402 Next visit scheduled: July 29, 2022	
Stamping:			
No			

INSPECTION REPORT

NO. R109220130.2

BV Job nr: KHO.INI.21.SA.

Description of the inspections carried out:**1. Introduction:**

The undersigned surveyor to Bureau Veritas acting within the scope of work along with the General condition which Regulate the intervention of the society IVS-Lifting/B&F Department at the Request of Sudhir Rentals on the purpose of Third Party Inspection .

2. Scope of Inspection :

a. Visual Inspection & Functional Test of GENERATOR

1- General Data

Equipment Type	Diesel Soundproof Generator
Manufacturer	LEYLAND
Serial No.	VEPL/2017-18/0130
Owner ID No	SG-246-160
Model:	VEPL-160-CDP
Rating	160 KW

2- Inspection and Test Results

Acceptance criteria	Result	Remarks
1. Document review (Original Declaration of Conformity)	Pass	Available
2. Visual inspection of Unit, wear, damage, loose connection /components, corrosion.	Pass	Found good condition.
3. Electrical,(conduct general inspection of wiring and connection cable termination, corrosion, damage	Pass	Found good condition.

➤ Conclusion:

The GENERATOR found in good condition at the time of Inspection.

Inspected by:

Mohamed Omara
LIFTING EQUIPMENT INSPECTOR



Issued at Al Khobar office on JAN 30, 2022

Checked by:

OPERATION TEAM LEADER

