


☐ Interim
☒ Final

INSPECTION REPORT

NO. R105220807.01

BV Job nr: KHO.INI.22.SA

PROJECT: Third Party Inspection for GENERATOR

Ref: KHO.INI.22.SA

BV Client: SUDHIR GENSETS

Manufacturer: VARADA ENERGIES PVT.LTD

SUPPLY / SUBJECT OF INSPECTION	SN / TAG Nr	QTY
Visual Inspection FOR GENERATOR	SG-310-60 VEPL/2018-19/0016	1

DOCUMENTS OF REFERENCE : See continuation sheet for additional documents: ☐ Yes ☐ No

Title	Reference n°	Rev.	Approved by
ORIGINAL DECLARATION OF CONFORMITY	-	-	VARADA ENERGIES

INSPECTIONS :

Results of inspection : ☒ Satisfactory ☐ UnsatisfactoryInspection place & Date or Period:**BAKER YARD 07 AUGUST 2022**Stage of inspection :

- ☐ Before manufacturing
☐ During manufacturing
☒ Final
☐ Packing

Type of inspection:

- ☐ Pre-inspection meeting
☐ Document and QC record review
☒ Visual examination, checks
☐ Witnessing tests
☐ Manufacturing progress status
☐ Vendor assessment
☒ Final inspection
☐ Packing

(for details see continuation sheet)

Stamping :☒ NoNon Conformities Reports (NCR):

o NCR's issued during reported period : N/A

o List of outstanding NCR's : N/A

Main Conclusions & Remarks: (for details see continuation sheet)

Third party visual inspection of 1 unit of GENERATOR was carried out and found satisfactory at the time of Inspection.

Valid Sticker Number : 01-32372**Next visit scheduled:** 06 FEB. 2023



INSPECTION REPORT

NO. R105220807.01

☐ Interim
☒ Final

Description of the inspections carried out:

1. Introduction:

The undersigned surveyor to Bureau Veritas acting within the scope of work along with the General condition which Regulate the intervention of the society IVS-Lifting/B&F Department at the Request of SUDHIR on the purpose of Third Party Inspection of 1 unit Of GENERATOR.

2. Attendees :

Mr. Hesham Elsaqa --- BV Inspector

3. Scope of Inspection :

a. Visual & Functional Inspection of GENERATOR

1- General Data

Equipment Type	GENERATOR
Serial Number	VEPL/2018-19/0016
Power	62.5 KW
YOM	2018

2- Inspection and Test Results

Acceptance criteria	Result	Remarks
1. Document review (Previous Report by universal inspection company)	Pass	Available
2. Visual inspection of Unit, wear, damage, loose connection/components, corrosion.	Pass	Found good condition.
3. Electrical, (conduct general inspection of wiring and connection cable termination, corrosion, damage	Pass	Found good condition.



NO. R105220807.01

The GENERATOR found in good condition at the time of Inspection.

Team Leader

Inspection centre: BUREAU VERITAS ALKHOBAR