

## CERTIFICATE OF THOROUGH EXAMINATION OF DIESEL GENERATOR

|                                           |                            |                                        |
|-------------------------------------------|----------------------------|----------------------------------------|
| Date of thorough examination : 22-07-2025 | Date of issue : 22-07-2025 | Report No. : <b>ESICO-LFT-R25-4945</b> |
|-------------------------------------------|----------------------------|----------------------------------------|

| Name & Address of employer       |                                                                                                                                   | Location             | Sticker No          | Standards               |
|----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------|-------------------------|
| SUDHIR EQUIPMENT RENTALS COMAPNY |                                                                                                                                   | Riyadh               | 6597                | SASO ISO 12100          |
| Equipment Identification No      | Equipment Description                                                                                                             | Safe Working Load(s) | Date of Manufacture | Manufacturer Name       |
| SG-338-60 OR VEPL/2018-19/0031   | AC GENERATOR<br>GENSET RATING: 62.5KVA<br>PHASE: 3 RATING V : 400<br>RATING FREQUENCY HZ: 60<br>RATING AMPS: 71<br>MASS : 1770 KG | N/A                  | 2018                | VARADA ENERGIES PVT LTD |

|                                                                                         |                                                                                                |                                                                   |                                                                                                |
|-----------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------------------------------------|------------------------------------------------------------------------------------------------|
| Is this the first examination after installaton or assembly at a new site or location?  | Yes <input type="checkbox"/> - <input type="checkbox"/> No <input checked="" type="checkbox"/> | Was the examination carried out within an interval of? - 6 Months | Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>                            |
| If the answer to the above question is YES, has the equipment been installed correctly? | Yes <input type="checkbox"/> - <input type="checkbox"/> No <input type="checkbox"/>            | In accordance with an examination scheme?                         | Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>                            |
|                                                                                         |                                                                                                | After the occurence of exceptional circumstances?                 | Yes <input type="checkbox"/> - <input type="checkbox"/> No <input checked="" type="checkbox"/> |

|                                                                                                                                                                               |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE                    |
| Is the above an existing or imminent danger to persons, Note: This is a reportable defect? N/A                                                                                |
| Is the above a defect which is not yet could become a danger to persons (if YES state the date by when) Yes by : N/A                                                          |
| Particulars of any repair, renewal or alteration required to remedy the defect identified above : N/A                                                                         |
| Particulars of any tests carried out as part of the examination (if none state NONE) : NONE                                                                                   |
| Observation/additional comments relative to this thorough examination : At the time of inspection generator was found to be of good condition and reliable for safe operation |



For confirmation scan QR code  
search with report number : **ESICO-LFT-R25-4945**

☒ Safe to operate

Next Inspection : 21-01-2026

Inspected by : Mohamed Askar Ali

