


☐ Interim
☒ Final

INSPECTION REPORT

NO. R105220814.03

BV Job nr: KHO.INI.22.SA

PROJECT: Third Party Inspection for GENERATOR

Ref: KHO.INI.22.SA

BV Client: SUDHIR GENSETS

Manufacturer: ASHOK LEYLAND

SUPPLY / SUBJECT OF INSPECTION	SN / TAG Nr	QTY
Visual Inspection FOR GENERATOR	SG-349-125	1

DOCUMENTS OF REFERENCE : See continuation sheet for additional documents: ☐ Yes ☐ No

Title	Reference n°	Rev.	Approved by
ORIGINAL DECLARATION OF CONFORMITY	-	-	ASHOK LEYLAND

INSPECTIONS :Inspection place & Date or Period:**SUDHIR YARD 14 AUGUST 2022**Stage of inspection :

- ☐ Before manufacturing
☐ During manufacturing
☒ Final
☐ Packing

Type of inspection:

- ☐ Pre-inspection meeting
☐ Document and QC record review
☒ Visual examination, checks
☐ Witnessing tests
☐ Manufacturing progress status
☐ Vendor assessment
☒ Final inspection
☐ Packing

(for details see continuation sheet)

Stamping:☒ No☐☐Results of inspection : ☒ Satisfactory ☐ UnsatisfactoryNon Conformities Reports (NCR):

o NCR's issued during reported period : N/A

o List of outstanding NCR's : N/A

Main Conclusions & Remarks: (for details see continuation sheet)

Third party visual inspection of 1 unit of GENERATOR was carried out and found satisfactory at the time of Inspection.

Valid Sticker Number : 01-32389**Next visit scheduled: 13 AUG. 2023**


☐ Interim
☒ Final

INSPECTION REPORT

NO. R105220814.03

Description of the inspections carried out:

1. Introduction:

The undersigned surveyor to Bureau Veritas acting within the scope of work along with the General condition which Regulate the intervention of the society IVS-Lifting/B&F Department at the Request of SUDHIR on the purpose of Third Party Inspection of 1 unit Of GENERATOR.

2. Attendees :

Mr. Hesham Elsaqa --- BV Inspector

3. Scope of Inspection :

a. Visual & Functional Inspection of GENERATOR



1- General Data

Equipment Type	GENERATOR
Model	VEPL-125-CDP
Engine Make	LEYLAND
Power	125

2- Inspection and Test Results

Acceptance criteria	Result	Remarks
1. Document review (Previous Report by universal inspection company)	Pass	Available
2. Visual inspection of Unit, wear, damage, loose connection/components, corrosion.	Pass	Found good condition.
3. Electrical, (conduct general inspection of wiring and connection cable termination, corrosion, damage	Pass	Found good condition.



☐ Interim
☒ Final

INSPECTION REPORT
NO. R105220814.03

➤ **Conclusion:**

The GENERATOR found in good condition at the time of Inspection.

Inspected by:

HESHAM ELSAQA
IVS-Lifting Inspection

Hesham Elsaqa



Checked by:

[Signature]
Team Leader

Date of issue: 17 AUGUST 2022

Inspection centre: BUREAU VERITAS ALKHOBAR