



### REPORT OF A THOROUGH EXAMINATION

Issue Date: 26-Apr-2026

|                                                             |                                        |                                               |
|-------------------------------------------------------------|----------------------------------------|-----------------------------------------------|
| Certificate Number: <b>ECI/SA/C-00894/26</b><br>Rev. No: 00 | Report Number: <b>131006</b>           | Sticker Number: <b>108367</b>                 |
| Date of Thorough Examination: <b>25-Apr-2026</b>            | Date of Expiration: <b>24-Oct-2026</b> | S.O.#: <b>DMM/04-26/001</b> Ref.#: <b>N/A</b> |

|                                                   |                                                                         |
|---------------------------------------------------|-------------------------------------------------------------------------|
| Client:<br><b>SUDHIR EQUIPMENT RENTAL COMPANY</b> | Address of Premises at Which the Examination Was Made:<br><b>DAMMAM</b> |
|---------------------------------------------------|-------------------------------------------------------------------------|

| Description and Identification of the Equipment:                                                                                                                                                                                                                                                                                                                                                | Load Test Detail | Safe Working Load(s) | Applied Load(s) |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|----------------------|-----------------|
| Equipment / Type : <b>MOBILE ELEVATING WORK PLATFORM / BOOM SUPPORTED - MANLIFT</b><br>Location of the Equipment : <b>DAMMAM YARD</b><br>Equipment ID No : <b>S28SJ-1650</b><br>Equipment Serial No : <b>B300001942</b><br>Model : <b>860SJ</b><br>Manufacturer / Date of Manufacture : <b>JLG / 2017</b><br>Applied Standard : <b>SASO-ISO-18893 : 2014 &amp; ANSI/SAIA A92.5 : 2006(2014)</b> | <b>N/A</b>       | <b>230 kg</b>        | <b>N/A</b>      |

|                                                                                                                                                                                  |  |                                                                                                                                                                                   |  |                                         |                                     |      |                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|-----------------------------------------|-------------------------------------|------|-------------------------------------|
| Examination after installation / In-Services                                                                                                                                     |  | Was the Examination carried out Within an interval of                                                                                                                             |  |                                         |                                     |      |                                     |
| <input type="checkbox"/> Initial <input checked="" type="checkbox"/> Periodic Inspection<br><input type="checkbox"/> Re-Inspection after Major Repair / Modification Or Overhaul |  | <input type="checkbox"/> 3 Months <input checked="" type="checkbox"/> 6 Months <input type="checkbox"/> 12 Months<br><input type="checkbox"/> After the exceptional circumstances |  |                                         |                                     |      |                                     |
| Additional Information about the equipment and Information / Description of the Parts / attachments with the equipment.<br><b>N/A</b>                                            |  |                                                                                                                                                                                   |  |                                         |                                     |      |                                     |
| <b>Description of the Load Test : N/A</b>                                                                                                                                        |  |                                                                                                                                                                                   |  |                                         |                                     |      |                                     |
| Pre Load Test NDT done by : <b>N/A</b>                                                                                                                                           |  | % of Load Applied : <b>N/A</b>                                                                                                                                                    |  | Post Load Test NDT done by : <b>N/A</b> |                                     |      |                                     |
| Result                                                                                                                                                                           |  |                                                                                                                                                                                   |  | PASS                                    | <input checked="" type="checkbox"/> | FAIL |                                     |
| Is the above a defect which is of immediate danger to persons?                                                                                                                   |  |                                                                                                                                                                                   |  | YES                                     |                                     | NO   | <input checked="" type="checkbox"/> |
| Is the above a defect which is not yet but could become a danger to persons?                                                                                                     |  |                                                                                                                                                                                   |  | YES by :                                |                                     | NO   | <input checked="" type="checkbox"/> |
| Particulars of any repair, renewal or alteration required to remedy the defect identified above:<br>N/A                                                                          |  |                                                                                                                                                                                   |  |                                         |                                     |      |                                     |
| Is this equipment safe to operate?                                                                                                                                               |  |                                                                                                                                                                                   |  | YES                                     | <input checked="" type="checkbox"/> | NO   |                                     |

**Note:** We thus attest that the aforementioned equipment has undergone a thorough Visual Inspection and /or Functional Test conducted by a qualified inspector in accordance with Engineering Corner for Inspection (E.C.I.) procedure / local / international standards.

**Liability:** The client or this assignee or supervisor in interest agrees to identify and hold harmless **Engineering corner for inspection Co.Ltd.** from and against any all claims, demands, lawsuits or actions for damages including legal fees to persons and/or property tangible, intangible or otherwise which may be against, **Engineering corner for inspection Co.Ltd.** incidental to, arising out of or in connection with the work to be done, services to be performed or material to be furnished hereunder except for those claims caused solely and completely by the negligence of **Engineering corner for inspection Co.Ltd.** its directors, others, employees or sub-contractors.

|                                                  |                                           |          |
|--------------------------------------------------|-------------------------------------------|----------|
| Inspected by: MOHAMED ABDUL BARICK<br>Signature: | Approved & Reviewed By: UMER ALI KHAN<br> | QR Code: |
|--------------------------------------------------|-------------------------------------------|----------|

|                                                                                  |                                                                                                                                  |           |                  |
|----------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------|-----------|------------------|
|  | <b>Engineering Corner for Inspection Company Limited</b><br><b>INSPECTION CHECKLIST</b><br><b>Mobile Elevating Work Platform</b> | Doc. No.  | ECIR - LFT - 109 |
|                                                                                  |                                                                                                                                  | Rev. No.  | 02               |
|                                                                                  |                                                                                                                                  | Rev. Date | 17-FEB-2026      |
|                                                                                  |                                                                                                                                  | Page No.  | 2 of 4           |

Issue Number : 02 & Issue Date : 03-FEB-2020


|                            |                                                                      |                              |                       |
|----------------------------|----------------------------------------------------------------------|------------------------------|-----------------------|
| <b>Equipment Owner</b>     | SUDHIR EQUIPMENT RENTAL COMPANY /                                    | <b>Report No. &amp; Date</b> | 131006<br>25-Apr-2026 |
| <b>Manufacturer / Year</b> | JLG / 2017                                                           | <b>Location</b>              | DAMMAM YARD           |
| <b>Type / Model</b>        | MOBILE ELEVATING WORK PLATFORM / BOOM<br>SUPPORTED - MANLIFT / 860SJ | <b>Equipment ID. No.</b>     | S28SJ-1650            |
| <b>Inspection Date</b>     | 25-Apr-2026                                                          | <b>Equipment Sr. No.</b>     | B300001942            |
| <b>Inspector Name</b>      | MOHAMED ABDUL BARICK                                                 | <b>Capacity / SWL</b>        | 230 kg                |
| <b>Standard</b>            | SASO-ISO-18893:2014                                                  | <b>Expiration Date</b>       | 24-Oct-2026           |

| Item No                                   | ITEM NAME                                                                            | PASS                                | FAIL | N/A | Item No                        | ITEM NAME                                                                                 | PASS                                | FAIL | N/A |
|-------------------------------------------|--------------------------------------------------------------------------------------|-------------------------------------|------|-----|--------------------------------|-------------------------------------------------------------------------------------------|-------------------------------------|------|-----|
| <b>DOCUMENTATION &amp; RECORDS</b>        |                                                                                      |                                     |      |     | 5.1                            | Wiring harness: No frayed wires, loose connections, or chafing.                           | <input checked="" type="checkbox"/> |      |     |
| 1.1                                       | Previous Inspection report                                                           | <input checked="" type="checkbox"/> |      |     | 5.2                            | Battery: Terminals clean and tight; fluid level correct; no corrosion.                    | <input checked="" type="checkbox"/> |      |     |
| 1.2                                       | Operator's manual (handbook) is present and legible.                                 | <input checked="" type="checkbox"/> |      |     | 5.3                            | Limit switches and sensors: Present, securely mounted, and appear functional.             | <input checked="" type="checkbox"/> |      |     |
| 1.3                                       | Maintenance and inspection records are available and up-to-date.                     | <input checked="" type="checkbox"/> |      |     | <b>POWER UNIT &amp; DRIVE</b>  |                                                                                           |                                     |      |     |
| 1.4                                       | All decals, warnings, and control markings are in place and legible.                 | <input checked="" type="checkbox"/> |      |     | 6.1                            | Engine/Motor: Fluids correct (oil, coolant, fuel).                                        | <input checked="" type="checkbox"/> |      |     |
| 1.5                                       | Manufacturer's safety bulletins have been checked and complied with (if applicable). | <input checked="" type="checkbox"/> |      |     | 6.2                            | Fuel system: No leaks.                                                                    | <input checked="" type="checkbox"/> |      |     |
| <b>STRUCTURAL INTEGRITY</b>               |                                                                                      |                                     |      |     | 6.3                            | Brakes: Function properly (including parking brake).                                      | <input checked="" type="checkbox"/> |      |     |
| 2.1                                       | Chassis and frame: No visible cracks, deformation, or damage.                        | <input checked="" type="checkbox"/> |      |     | 6.4                            | Steering: Operates smoothly with no excessive play.                                       | <input checked="" type="checkbox"/> |      |     |
| 2.2                                       | Extending structure (boom, mast, scissors): No cracks, distortion, or weld damage.   | <input checked="" type="checkbox"/> |      |     | 6.5                            | Wheels and tires: Proper inflation (if pneumatic), no damage.                             | <input checked="" type="checkbox"/> |      |     |
| 2.3                                       | Work platform floor: Clean, no holes, anti-skid surface intact.                      | <input checked="" type="checkbox"/> |      |     | 6.6                            | Wheel nuts/fasteners: Torqued properly and present.                                       | <input checked="" type="checkbox"/> |      |     |
| 2.4                                       | Guardrail system: Top rail, mid-rail, and toe boards are secure and undamaged.       | <input checked="" type="checkbox"/> |      |     | <b>FUNCTIONAL TEST</b>         |                                                                                           |                                     |      |     |
| 2.5                                       | Entrance gate / chain: Self-closing and self-latching (if so equipped).              | <input checked="" type="checkbox"/> |      |     | 7.1                            | Ground Controls: All functions operate smoothly (lift, lower, extend, rotate).            | <input checked="" type="checkbox"/> |      |     |
| 2.6                                       | Anchor points (for fall arrest): Present, undamaged, and clearly marked.             | <input checked="" type="checkbox"/> |      |     | 7.2                            | Platform Controls: All functions operate smoothly from platform.                          | <input checked="" type="checkbox"/> |      |     |
| 2.7                                       | Fasteners, pins, and shafts: Secured, no visible wear or distortion.                 | <input checked="" type="checkbox"/> |      |     | 7.3                            | Emergency Stop: Functions from both ground and platform.                                  | <input checked="" type="checkbox"/> |      |     |
| <b>STABILIZATION &amp; SUPPORT</b>        |                                                                                      |                                     |      |     | 7.4                            | Auxiliary/Manual Descent: Operates correctly and lowers platform.                         | <input checked="" type="checkbox"/> |      |     |
| 3.1                                       | Stabilizers/Outriggers: Deploy smoothly, no visible damage or leaks.                 | <input checked="" type="checkbox"/> |      |     | 7.5                            | Drive and steer functions: Operate correctly (test at low and high speed, if applicable). | <input checked="" type="checkbox"/> |      |     |
| 3.2                                       | Pad/Foot plates: Present, not worn out, and swivel freely.                           | <input checked="" type="checkbox"/> |      |     | 7.6                            | Tilt alarm/indicator: Functions correctly (simulate slope if safe).                       | <input checked="" type="checkbox"/> |      |     |
| 3.3                                       | Locking devices: All pins, latches, or locks function and secure properly.           | <input checked="" type="checkbox"/> |      |     | 7.7                            | Load sensing system (if equipped): No fault codes visible.                                | <input checked="" type="checkbox"/> |      |     |
| 3.4                                       | Oscillating axle: Locking mechanism functions (if applicable).                       | <input checked="" type="checkbox"/> |      |     | 7.8                            | Horn and Alarms: Audible and functioning.                                                 | <input checked="" type="checkbox"/> |      |     |
| <b>MECHANICAL &amp; HYDRAULIC SYSTEMS</b> |                                                                                      |                                     |      |     | 7.9                            | Pothole protection system (Scissor lifts): Deploys automatically when elevated.           | <input checked="" type="checkbox"/> |      |     |
| 4.1                                       | Hydraulic hoses and fittings: No leaks, abrasion, kinks, or bubble/swelling.         | <input checked="" type="checkbox"/> |      |     | 7.10                           | Platform overload indicator (if equipped): Functions correctly.                           | <input checked="" type="checkbox"/> |      |     |
| 4.2                                       | Hydraulic oil level: Correct (check sight glass/dipstick).                           | <input checked="" type="checkbox"/> |      |     | <b>SPECIFIC SAFETY DEVICES</b> |                                                                                           |                                     |      |     |
| 4.3                                       | Cylinders: No visible damage, leaks, or rod scoring.                                 | <input checked="" type="checkbox"/> |      |     | 8.1                            | Lanyard attachment points: Secure and undamaged.                                          | <input checked="" type="checkbox"/> |      |     |
| 4.4                                       | Lubrication: All pivot points and moving parts are greased/lubricated.               | <input checked="" type="checkbox"/> |      |     | 8.2                            | Motion alarms / beacon lights: Working (if applicable).                                   | <input checked="" type="checkbox"/> |      |     |
| 4.5                                       | Cables and wire ropes: No fraying, broken strands, or corrosion; properly tensioned. | <input checked="" type="checkbox"/> |      |     | 8.3                            | Insulating boom (if applicable): Inspected per IEC/TS 61813.                              | <input checked="" type="checkbox"/> |      |     |
| 4.6                                       | Chains: Properly tensioned, lubricated, and no visible wear/stretch.                 | <input checked="" type="checkbox"/> |      |     | 8.4                            | Communication system (platform to ground): Working (if required).                         | <input checked="" type="checkbox"/> |      |     |
| <b>ELECTRICAL SYSTEM</b>                  |                                                                                      |                                     |      |     |                                |                                                                                           |                                     |      |     |

|                                            |                                       |
|--------------------------------------------|---------------------------------------|
| <b>Inspected By : MOHAMED ABDUL BARICK</b> | <b>Customer Representative : ARIF</b> |
|--------------------------------------------|---------------------------------------|



Certificate Number: ECI/SA/C-00894/26





**ECL 108367**

**Capacity : 230 kg**

**Equipment No. : S28SJ-1650**

**Serial No. : B300001942**

**Inspected Date : 25-Apr-2026**

**Next Inspection : 24-Oct-2026**

**Inspector : MOHAMED ABDUL BARICK**

**P.O.Box 235 Rastanura 31941 Kingdom of Saudi Arabia**

**Tel.: (013) 667-6999 / 667-6895 Fax #:(013) 667-6894**

**E-mail Address: [eci@eccgroupksa.com](mailto:eci@eccgroupksa.com)**