

INSPECTION CERTIFICATE

DIESEL ARTICULATED BOOM

CLIENT NAME : SUDHIR EQUIPMENT RENTAL CO		WORK ORDER : WR-YAS-345	
EQUIPMENT DESCRIPTION : DIESEL OPERATED MANLIFT WITH CAPACITY OF 320 KG		CERTIFICATE NO : YAS-CRT-1346	
		STICKER NO : 12676	
DATE OF INSPECTION : 10-May-2026		NEXT INSPECTION DUE : 09-Nov-2026	
PREVIOUS INSPECTION : 03-Nov-2025		PREVIOUS INSPECTION DETAILS : BUREAU VERITAS	
MANUFACTURER : DINGLI		MODEL/TYPE : BA20CRT2	
SERIAL NO : BARC024I00529		OWNER ID : S20AD-1774	
CHECKLIST NO. : 1122		MANUFACTURED YEAR : 2024	
TYPE OF INSPECTION : PERIODIC AND FUNCTIONAL INSPECTION		LOCATION : RIYADH	
REFERENCE STANDARDS : BS EN 280-1:2022			
CAPACITY / SWL:	320 KG		
NO OF PERSONS:	2 PERSONS + 160 KG EQUIPMENT		
TEST LOAD:	N/A		
MAX HORIZONTAL REACH:	N/A		
PLATFORM HEIGHT:	20.15 METER		
OUTRIGGER:	N/A		
Is this the first examination after installation or assembly at a new site or location ?	☐ Yes ☒ No	Within an interval of Months?	☒ 6 ☐ 12
If the answer to the above question is YES has the equipment been installed correctly ?	☐ Yes ☒ No	In accordance with an examination scheme ?	☐ Yes ☒ No
After the occurrence of exceptional circumstances ?		☐ Yes ☒ No	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE)		NONE	
Is the above a defect which is of immediate danger to persons		☒ Yes ☐ No	
Is the above a defect which is not yet but could become a danger to persons:(If YES state the date by when)		NONE	
Particulars of any tests carried out as part of the examination: (If none state NONE)		NONE	
RESULT:	☒ PASS ☐ FAIL	IS THIS EQUIPMENT FIT FOR PURPOSE?	☒ Yes ☐ No
REMARKS/RECOMMENDATION THIS IS TO CERTIFY THAT THE MAN LIFT HAS BEEN FUNCTIONALLY INSPECTED IN ACCORDANCE WITH INTERNATIONALLY RECOGNIZED STANDARDS ON THE INSPECTION DATE. THE EQUIPMENT IS FREE FROM EXTERNAL DAMAGE, AND THE EQUIPMENT IS FOUND TO BE IN SATISFACTORY CONDITION.			
Date Of Report: 10/5/2026			

Approved By : ABDUL HALEEM

Authorized Inspector : MUHAMMAD ADNAN

WORKORDER NO: WR-YAS-345
CERTIFICATE NO: YAS-CRT-1346
WORKORDER NO: WR-YAS-345
CERTIFICATE NO: YAS-CRT-1346
WORKORDER NO: WR-YAS-345
CERTIFICATE NO: YAS-CRT-1346



Note : This certificate becomes void if the equipment is altered, repaired, or modified without authorization. The equipment owner is solely responsible for safe operation and maintenance. The company accepts no liability for damages or failures arising from negligence, poor maintenance, or conditions not detectable during routine inspection.