

CERTIFICATE OF LOAD TEST THOROUGH EXAMINATION OF MOBILE ELEVATING WORK PLATFORM

Date of thorough examination : 21-06-2026	Date of issue : 21-06-2026	Report No. : ESICO-LFT-R26-9415
---	----------------------------	--

Name & Address of employer	Location	Sticker	Standards
SUDHIR EQUIPMENT RENTALS	2ND INDUSTRIAL DAMMAM	11067	SASO GSO EN 280 & ANSI A92.6

Equipment Identification No	Equipment Description	Safe Working Load(s)	Date of Manufacture	Manufacturer Name
SD10ESL-1941 OR JPAC024I04501	SCISSOR LIFT MODEL: JCPT1008AC TYPE: ELECTRIC WORKING HEIGHT: 10 M PLATFORM WIDTH: 0.81 M PLATFORM LENGTH: 2.27 M TRANSPORT HEIGHT: 2 M TRANSPORT LENGTH: 2.48 M	WEIGHT: 2250 KG	2024	DINGLI

Is this the first examination after installaton or assembly at a new site or location?	Yes - No ☒	Was the examination carried out within an interval of?	- 6 Months
If the answer to the above question is YES, has the equipment been installed correctly?	Yes - No -	In accordance with an examination scheme?	Yes ☒ No -
		After the occurence of exceptional circumstances?	Yes - No ☒

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE

Is the above an existing or imminent danger to persons, Note: This is a reportable defect? No

Is the above a defect which is not yet could become a danger to persons (if YES state the date by when) Yes by : N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above : NONE

Particulars of any tests carried out as part of the examination (if none state NONE) : VISUAL INSPECTION

Observation/additional comments relative to this thorough examination : AT THE TIME OF INSPECTION, THE NAME ABOVE THE EQUIPMENT WAS SAFE FOR OPERATION



For confirmation scan QR code
search with report number : **ESICO-LFT-R26-9415**

☒ Safe to operate

Next Inspection : 20-12-2026

Inspected by : Eric Kwesi Ankomanyi

