

CERTIFICATE OF LOAD TEST THOROUGH EXAMINATION OF MOBILE ELEVATING WORK PLATFORM (Revision 2)

Date of thorough examination: 20-08-2025		Date of issue: 20-08-2025		Report No.: ESICO-LFT-R25-5563	
Name & Address of employer		Location	Sticker No	Standards	
SUDHIR EQUIPMENT RENTALS COMAPNY		SANAYA-2	7215	SASO GSO EN 280 & ANSI A92.5	

Equipment Identification No	Equipment Description	Safe Working Load(s)	Date of Manufacture	Manufacturer Name
S16AD-2237 OR BARC024L00744	MAN LIFT MODEL: BA16CRT2 TYPE: AWP SERIAL NO: BARC024L00744 PLAT FORM HEIGHT: 16MTR CAPACITY: 250KG	250KG(2P)	UNKNOWN	DINGLI

Is this the first examination after installation or assembly at a new site or location?	Yes	-	No	☒	Was the examination carried out within an interval of? - 6 Months	Yes	☒	No	-
If the answer to the above question is YES, has the equipment been installed correctly?	Yes	-	No	-	In accordance with an examination scheme?	Yes	☒	No	-
					After the occurrence of exceptional circumstances?	Yes	-	No	☒

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE	
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?	No
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)	Yes by : N/A
Particulars of any repair, renewal or alteration required to remedy the defect identified above : NONE	
Particulars of any tests carried out as part of the examination (if none state NONE) : VISUAL INSPETION AND FUNCTIONAL TEST	
Observation/additional comments relative to this thorough examination : AT THIS TIME OF INSPECTION MACHINE WAS SATISFACTRY.	



☒ **Safe to operate**
Next Inspection: 19-02-2026

Inspected by: HENDRICKS



For confirmation scan QR code

Search with report number : **ESICO-LFT-R25-5563**

Checklist - Mobile Elevated Work Platform Inspection

Item Name	Sat	Unsat	N/A	Comments
UNIT INSPECTION ITEM AND DESCRIPTION				
The manufacturer's operations manual is stored on the unit	✓	-	-	
Operating and emergency controls are in proper working condition (including emergency stop mechanism)	✓	-	-	
Functional platform drive controls are in proper working condition	✓	-	-	
The emergency lowering mechanism operates properly	✓	-	-	
Lower operating controls successfully override the upper controls	✓	-	-	
Both upper and lower controls are adequately protected from inadvertent operation	✓	-	-	
The control panel is clean, and all buttons/switches are clearly visible	✓	-	-	
All switches and mechanical guards are in good condition and properly installed	✓	-	-	
All safety indicator lights work	✓	-	-	
All drive controls function properly and are accurately labelled	✓	-	-	
Motion alarms function properly	✓	-	-	
Safety decals are in place and readable	✓	-	-	
All guard rails are sound and in place, including basket chains	✓	-	-	
Work platform and extension slides are clean, dry, and clear of debris	✓	-	-	
Models with platform extensions: slides in and out freely with functioning safety locking pins	✓	-	-	
Inspect for defects, including cracked welds, fuel leaks, hydraulic leaks, damaged control cables or wire harness, etc.	✓	-	-	
Tires and wheels are in good condition with adequate air pressure if pneumatic	✓	-	-	
Braking devices are operating properly	✓	-	-	
Oil level/Hydraulic Oil Level/Fuel Level/Coolant Level is acceptable	✓	-	-	
Battery Charge is acceptable	✓	-	-	
Outriggers in place or functioning, and associated alarms working	✓	-	-	



For confirmation scan QR code

Search with report number : **ESICO-LFT-R25-5563**

✓ **Safe to operate**

Next Inspection: 19-02-2026

Inspected by: HENDRICKS





شركة مساندة الإعمار للفحص Emaar Support Inspection Co.

6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia

Tel: +966 507259023, +966 136670779, 055 8889186, 050 0484444

Email: info@esico.com.sa | www.esico.com.sa | C.R: 2054100036



أرامكو السعودية
saudi aramco
10056897



الشركة السعودية للكهرباء
Saudi Electricity Company
05022531

