



CERTIFICATE OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination	Date of Certificate	Certificate number	Sticker Number
16- Jan- 2025	16- Jan- 2025	UIC/DUB/20222958	143513
Next Examination Due Date	Date of last thorough examination	Reference Standard	Order No
15- Jan- 2026	16- Jan- 2025	BS EN 280-1:2022	-
Name and Address of Customer		Address of Examination	
SUDHIR RENTALS		DUBA - KSA	
Description and identification of the equipment		Equipment ID	Safe Working Load
SCISSOR LIFT Make: DINGLI Model: 212AC ID NO: SD12ESL-792 Drive Speed - Platform Elevated: 0.80 km/h, Maximum Lift Height: 10.0 m.		SD12ESL-792	320 kg
Is this the first Examination after installation or assembly at a new site or location?	NO	Was the Examination carried out within an interval of 6 months?	NO
Has the equipment been installed correctly?	YES	Was the Examination carried out within an interval of 12 months?	YES
In accordance with an Examination Scheme?	NO	After the occurrence of exceptional circumstances?	NO
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:			
NONE			
Is the above an existing or imminent danger to persons?			NO
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when)			NONE
Particulars of any repair, renewal or alteration required to remedy the defect identified above:			
NONE			
Particulars of any tests carried out as part of the examination. And standard applied			
This Scissor Lift has been Visual & Functional Examined in accordance with BS EN 280-1:2022.			
IS THIS EQUIPMENT SAFE TO OPERATE?		YES	Stamp
Name and Signature of the person issue this certificate.	Name and Signature of the person authenticating this certificate.		
Name: AFRIDI Signature: A. AFRIDI	Name: ABDUL KHALEEL Signature: R. A. KHALEEL		
Comments/Remarks:			
At the time of inspection, the equipment was found satisfactory and free from any defects or damage and found safe for use. UNIVERSAL INSPECTION CO. LTD. holds no responsibility for any damage occurring after the inspection date due to improper use Pertaining to operation as per the manufacturer's manual, maintenance, and servicing. This Thorough Examination was within the limits of Client's specifications.			