



INSPECTION REPORT

NO. R110210831.01

☐ Interim
☒ Final

BV Job nr: KHO.INI.19.206.SA.

PROJECT: Third Party Inspection for GENERATOR

Ref: KHO.INI.19.206.SA

BV Client: Sudhir Rentals

P/o nr: N/A
(client to BV)

Manufacturer: WELLAND POWER

SUPPLY / SUBJECT OF INSPECTION	SN / TAG Nr	Owner ID No	QTY
VISUAL EXAMINATION AND FUNCTIONAL TEST OF GENERATOR	UK20035-9000053	SG-111-500	1

DOCUMENTS OF REFERENCE : See continuation sheet for additional documents: ☐ Yes ☐ No

Title	Reference n°	Rev.	Approved by	Date
EQUIPMENT DATA SHEET	-	-	WELLAND POWER	-

INSPECTIONS :

Inspection place & Date or Period:DAMMAM SUDHIR YARD.
AUGUST 31, 2021Stage of inspection :

- ☐ Before manufacturing
☐ During manufacturing
☒ Final
☐ Packing

Type of inspection:

- ☐ Pre-inspection meeting
☐ Document and QC record review
☒ Visual examination, checks
☐ Witnessing tests
☐ Manufacturing progress status
☐ Vendor assessment
☒ Final inspection
☐ Packing

(for details see continuation sheet)

Stamping :

- ☒ No ☐  ☐ 

Results of inspection : ☒ Satisfactory ☐ UnsatisfactoryNon Conformities Reports (NCR):

o NCR's issued during reported period : N/A

o List of outstanding NCR's : N/A

Main Conclusions & Remarks: (for details see continuation sheet)

Third party visual inspection and functional test of one unit of Generator was carried out and found satisfactory at the time of Inspection.

Valid Sticker Number : LTF-S-01-26869

Next visit scheduled: AUG 30, 2022



INSPECTION REPORT

NO. R110210831.01

☐ Interim
☒ Final

BV Job nr: KHO.INI.19.206.SA.

Description of the inspections carried out:

1. Introduction:

The undersigned surveyor to Bureau Veritas acting within the scope of work along with the General condition which Regulate the intervention of the society IVS Department at the Request of Sudhir Rental Co. on the purpose of Third Party Inspection.

2. Scope of Inspection :

Visual Inspection & Functional Test of Generator.

1- General Data	
Equipment Type	Generator
Manufacturer	Welland Power
Model	WP500
Serial No.	UK20035-9000053
Alternator No	A15H355052
Owner ID No	SG-111-500
Rating	500 kVA / 400 kW

3- Inspection and Test Results


Acceptance criteria	Result	Remarks
1. Document review (Original Declaration of Conformity)	Pass	Available
2. Visual inspection of Unit-leaks, wear, damage, loose connection/components, corrosion.	Pass	Found good condition.
3. Check air filter and engine oil level	Pass	Found good condition.

➤ Conclusion:

The Generator was found satisfactory and in good running condition at the time of Inspection.

Surveyor's name: Ahmed ZoneFull

Signature:



Authorized by team leader :

Signature:

Issued at Al Khobar office on 31 August 2021