


☐ Interim
☒ Final

INSPECTION REPORT

NO. R114220614.01

BV Job nr: KHO.IVS.2018-53

PROJECT: Third Party Inspection for Tower Light	Ref: KHO.IVS.2018-53
BV Client: Sudhir	P/o nr: N/A (client to BV)
Manufacturer: Wacker Neuson	

SUPPLY / SUBJECT OF INSPECTION	SN / TAG Nr	QTY
VISUAL EXAMINATION AND FUNCTIONAL TEST OF Tower Light.	1KD2250 – 18200942 STL-028	1

DOCUMENTS OF REFERENCE : See continuation sheet for additional documents: ☐ Yes ☐ No

Title	Reference n°	Rev.	Approved by	Date
EQUIPMENT DATA SHEET	--	-	-	-

INSPECTIONS :**Inspection place & Date or Period:**

KHARJ 14, June, 2022

Stage of inspection :

- ☐ Before manufacturing
☐ During manufacturing
☒ Final
☐ Packing

Type of inspection:

- ☐ Pre-inspection meeting
☐ Document and QC record review
☒ Visual examination, checks
☐ Witnessing tests
☐ Manufacturing progress status
☐ Vendor assessment
☒ Final inspection
☐ Packing

(for details see continuation sheet)

Stamping:☒ No☐☐**Results of inspection :** ☒ Satisfactory ☐ Unsatisfactory**Non Conformities Reports (NCR):**

o NCR's issued during reported period : N/A

o List of outstanding NCR's : N/A

Main Conclusions & Remarks: (for details see continuation sheet)Third party visual inspection of 1 unit of **Tower Light** was carried out and found satisfactory at the time of Inspection.**Valid Sticker Number :** LFT-S-01-29593**Next visit scheduled:** Dec, 13 , 2022

☐ Interim
☒ Final

INSPECTION REPORT

NO. R114220614.01

BV Job nr: KHO.IVS.2018-53

Description of the inspections carried out:

1. Introduction:

The undersigned surveyor to Bureau Veritas acting within the scope of work along with the General condition which Regulate the intervention of the society IVS-Lifting/B&F Department at the Request of Sudhir Company on the purpose of Third Party Inspection of One **Tower Light** with Model number: **LTS8K** and S/N: 1KD2250 / 18200942

2. Attendees :

3. Scope of Inspection :

a. Visual Inspection & Functional Test of **Tower Light**.

1- General Data

Equipment Type	Tower Light
Manufacturer	Wacker Neuson
Model	LTS8K
Serial Number :	1KD2250 / 18200942



INSPECTION REPORT

NO. R114220614.01

BV Job nr: KHO.IVS.2018-53

3- Inspection and Test Results

Acceptance criteria	Result	Remarks
1. Document review (Original Declaration of Conformity)	Pass	Available
2. Visual inspection of Unit-leaks, wear, damage, loose connection/components, corrosion.	Pass	Found good condition.
3. Check engine oil level (check for proper oil level and oil operating pressure.	Pass	Found good condition.
4. Check air filter	Pass	Found good condition.
5. Electrical,(conduct general inspection of wiring and connection cable termination, corrosion, damage	Pass	Found good condition.
6. Prime mover / Generator (Check for debris, foreign objects, looser broken fittings; check guards and components; look for any unusual condition of vibration, leakage, noise, temperature or deterioration.	Pass	Found good condition.
7. Check engine drive belts, fan coupling device-tension wear, whether cracking, damage.	Pass	Found good condition.
8. Check emergency switches.	Pass	Found good condition.

➤ **Conclusion:**The **Tower Light** found in good condition at the time of Inspection.

Inspected by:

Checked by:

ALI ALHOMOOD
IVS- Inspector


IVS- Inspection Team Leader

Date of issue: 16 June 2022

Inspection centre: BUREAU VERITAS ALKHOBAR