


☐ Interim  
☒ Final

## INSPECTION REPORT

NO. R109221004.02

BV Job nr: KHO.INI.22.SA.

|                                                 |                                         |
|-------------------------------------------------|-----------------------------------------|
| PROJECT: Third Party Inspection for Tower Light | Ref: KHO.INI.22.SA.                     |
| BV Client: Sudhir Equipment Rental co.          | P/o nr: N/A<br>(client to BV)           |
| Manufacturer: WACKER NEUSON                     | P/o nr: N/A<br>(client to Manufacturer) |

| SUPPLY / SUBJECT OF INSPECTION                  | SN / TAG Nr | Owner ID No.: | QTY |
|-------------------------------------------------|-------------|---------------|-----|
| VISUAL EXAMINATION AND FUNCTIONAL TEST WAS DONE | 18201356    | STL-032       | 1   |

DOCUMENTS OF REFERENCE : See continuation sheet for additional documents: ☐ Yes ☐ No

| Title | Reference n° | Rev. | Approved by | Date |
|-------|--------------|------|-------------|------|
| N/A   | N/A          | -    | N/A         | -    |

## INSPECTIONS :

Inspection place & Date or Period:Sudhir Rental Warehouse,  
DAMMAM YARD

OCT 04, 2022

Stage of inspection :

- ☐ Before manufacturing  
☐ During manufacturing  
☒ Final  
☐ Packing

Type of inspection:

- ☐ Pre-inspection meeting  
☐ Document and QC record review  
☒ Visual examination, checks  
☐ Witnessing tests  
☐ Manufacturing progress status  
☐ Vendor assessment  
☒ Final inspection  
☐ Packing

(for details see continuation sheet)

Stamping :☒ NoResults of inspection : ☒ Satisfactory ☐ UnsatisfactoryNon Conformities Reports (NCR):

o NCR's issued during reported period : N/A

o List of outstanding NCR's : N/A

Main Conclusions & Remarks: (for details see continuation sheet)

Visual inspection and Function Test done for Tower Light and found satisfactory at the time of Inspection.

Valid Sticker Number : 01-34352

Next visit scheduled: OCT 03, 2023

## INSPECTION REPORT

NO. R109221004.02

BV Job nr: KHO.INI.21.SA.

Description of the inspections carried out:**1. Introduction:**

The undersigned surveyor to Bureau Veritas acting within the scope of work along with the General condition which Regulate the intervention of the society IVS-Lifting/B&F Department at the Request of Sudhir Rentals on the purpose of Third Party Inspection .

**2. Scope of Inspection :**

a. Visual Inspection &amp; Functional Test of Tower Light

**1- General Data**

|                |               |
|----------------|---------------|
| Equipment Type | Tower Light   |
| Manufacturer   | WACKER NEUSON |
| Model          | LTS8K         |
| Serial No.     | 182011356     |
| Owner ID No    | STL-032       |

**2- Inspection and Test Results**

| Acceptance criteria                                                                                     | Result | Remarks               |
|---------------------------------------------------------------------------------------------------------|--------|-----------------------|
| 1. Document review (Original Declaration of Conformity)                                                 | Pass   | Available             |
| 2. Visual inspection of Unit, wear, damage, loose connection /components, corrosion.                    | Pass   | Found good condition. |
| 3. Electrical,(conduct general inspection of wiring and connection cable termination, corrosion, damage | Pass   | Found good condition. |

**➤ Conclusion:**

The Equipment found in good condition at the time of Inspection.

Inspected by:

**MOHAMED OMARA**  
Senior Lifting Inspector

Issued at Al Khobar office on OCT 04, 2022

Checked by:

OPERATION TEAM LEADER

