


☐ Interim
☒ Final

INSPECTION REPORT

NO. R109220214.02

BV Job nr: KHO.INI.22.SA.

PROJECT: Third Party Inspection for Tower Light	Ref: KHO.INI.22.SA.
BV Client: Sudhir Equipment Rental co.	P/o nr: N/A (client to BV)
Manufacturer: WACKER NEUSON	P/o nr: N/A (client to Manufacturer)

SUPPLY / SUBJECT OF INSPECTION	SN / TAG Nr	Owner ID No.:	QTY
VISUAL EXAMINATION AND FUNCTIONAL TEST WAS DONE	18201836	STL-61	1

DOCUMENTS OF REFERENCE : See continuation sheet for additional documents: ☐ Yes ☐ No				
Title	Reference n°	Rev.	Approved by	Date
N/A	N/A	-	N/A	-

INSPECTIONS : <u>Inspection place & Date or Period:</u> Sudhir Rental Warehouse, DAMMAM YARD Feb 14 , 2022 Stage of inspection : ☐ Before manufacturing ☐ During manufacturing ☒ Final ☐ Packing Type of inspection: ☐ Pre-inspection meeting ☐ Document and QC record review ☒ Visual examination, checks ☐ Witnessing tests ☐ Manufacturing progress status ☐ Vendor assessment ☒ Final inspection ☐ Packing (for details see continuation sheet) Stamping: ☒ No ☐ ☐	Results of inspection : ☒ Satisfactory ☐ Unsatisfactory Non Conformities Reports (NCR): o NCR's issued during reported period : N/A o List of outstanding NCR's : N/A Main Conclusions & Remarks: (for details see continuation sheet) Visual inspection and Function Test done for Tower Light and found satisfactory at the time of Inspection. Valid Sticker Number : 01-29410 Next visit scheduled: FEB 13 , 2023
--	--


☐ Interim
☒ Final

INSPECTION REPORT

NO. R109220214.02

BV Job nr: KHO.INI.21.SA.

Description of the inspections carried out:**1. Introduction:**

The undersigned surveyor to Bureau Veritas acting within the scope of work along with the General condition which Regulate the intervention of the society IVS-Lifting/B&F Department at the Request of Sudhir Rentals on the purpose of Third Party Inspection .

2. Scope of Inspection :

a. Visual Inspection & Functional Test of Tower Light

1- General Data

Equipment Type	Tower Light
Manufacturer	Wacker Neuson
Model	LTS4K
Serial No.	18201836
Owner ID No	STL-061

2- Inspection and Test Results

Acceptance criteria	Result	Remarks
1. Document review (Original Declaration of Conformity)	Pass	Available
2. Visual inspection of Unit, wear, damage, loose connection /components, corrosion.	Pass	Found good condition.
3. Electrical,(conduct general inspection of wiring and connection cable termination, corrosion, damage	Pass	Found good condition.

> Conclusion:

The Equipment found in good condition at the time of Inspection.

Inspected by:

MOHAMED OMARA
Lifting Equipment Inspector



Checked by:
OPERATION TEAM LEADER

Issued at Al Khobar office on **FEB 15, 2022**