

Ownership Certificate

To Whom It May Concern

This is to certify that the following equipment mentioned below are the sole owned by Sudhir Equipment Rental Company

Equipment	Forklift
Brand / Make	TOYOTA
Asset ID	SE3FLT-033
Model Number	8FBJ35
Serial Number	8FBJ35-13005
Engine Serial Number	
Capacity	3.5 TON ELECTRIC
Manufacturing Year	2022

Mansoor Ali

Branch Manager

Sudhir Equipment Rental Company

Dammam- KSA





Certificate of Insurance

Policy Holder Name
Policy Number
Original Policy Period

Sudhir Equipment Rental Company
5/EP/30425/0/0
05/04/2026 to 04/04/2027

اسم حامل الوثيقة
رقم الوثيقة
فترة الوثيقة الأصلية

Gulf Insurance Group certifies that above client is holding Contractor's Plant & Machinery Insurance Policy for the below mentioned Equipment in accordance with the above mentioned Insurance Policy:

تشهد مجموعة الخليج للتأمين بأن العميل المذكور أعلاه يحمل وثيقة تأمين على معدات والآلات المقاولين للمعدة المذكورة أدناه، وذلك وفقاً لشروط وثيقة التأمين المذكورة أعلاه:

Asset ID	:	SE3FLT-033	:	معرف الأصل
Brand	:	Toyota	:	العلامة التجارية
Type	:	8FBJ35	:	النوع
Model	:	Forklift	:	الطراز
Manufacturing Year	:	0	:	سنة الصنع
Equipment Serial Number	:	8FBJ35-13005	:	الرقم التسلسلي للمعدة
Insurance Effective Date	:	05/04/2026	:	تاريخ سريان التأمين

This Certificate has been issued upon Insureds request as per all terms and conditions, exclusions, warranties mentioned in the policy.

تم إصدار هذه الشهادة بناء على طلب المؤمن له وذلك حسب الشروط والاستثناءات والاشتراطات المذكورة في الوثيقة

Al Khobar : 01st April 2026

Signature of Insurer's Authorized Representative



PUBLIC

Gulf Insurance Group

A Saudi joint stock company | Paid-up capital 500 Million Saudi Riyals
Licensed by No (TMN/25/20101) | Commercial Registration No.1010271203
3528 King Abdullah Bin Abdulaziz Road, Al Nuzha District
Unit No. 25 | Riyadh 12471 - 6378
Toll free 8001160020 | Website www.gig.sa
Regulated and Supervised by The Saudi Central Bank

مجموعة الخليج للتأمين

شركة مساهمة سعودية | رأس المال 500,000,000 ريال سعودي
مرخص لها برقم ترخيص (ت م ن/25/20101) | سجل تجاري رقم 1010271203
3528 طريق الملك عبد الله بن عبدالعزيز، حي النزهة
رقم الوحدة 25 | الرياض 12471 - 6378
www.gig.sa الرقم المجاني 8001160020 | الموقع الإلكتروني
خاضعة لرقابة وإشراف البنك المركزي السعودي



REPORT OF A THOROUGH EXAMINATION

Issue Date: 23-Jun-2026

Certificate Number: ECI/SA/C-03089/26 Rev. No: 00	Report Number: 134479	Sticker Number: 110066
Date of Thorough Examination: 22-Jun-2026	Date of Expiration: 21-Dec-2026	S.O.#: DMM/06-26/001 Ref.#: N/A

Client: SUDHIR EQUIPMENT RENTAL COMPANY	Address of Premises at Which the Examination Was Made: DAMMAM
---	---

Description and Identification of the Equipment:	Load Test Detail	Safe Working Load(s)	Applied Load(s)
Equipment / Type : HEAVY EQUIPMENT / FORKLIFT Location of the Equipment : SIEMENS WARE HOUSE, DAMMAM Equipment ID No : SE3FLT-033 Equipment Serial No : 8FBJ35-13005 Model : 8FBJ35 Manufacturer / Date of Manufacture : TOYOTA / 2020 Applied Standard : ANSI / ITSDF B56.6 - 2021 & SASO ISO 5057-1993	N/A	3500 kg	N/A

Examination after installation / In-Services		Was the Examination carried out Within an interval of					
☐ Initial ☒ Periodic Inspection ☐ Re-Inspection after Major Repair / Modification Or Overhaul		☐ 3 Months ☒ 6 Months ☐ 12 Months ☐ After the exceptional circumstances					
Additional Information about the equipment and Information / Description of the Parts / attachments with the equipment. MAX LIFTING HEIGHT : 4300 mm. LOAD CENTER : 500 mm FORK SL,N: 316010014							
Description of the Load Test : N/A							
Pre Load Test NDT done by : N/A		% of Load Applied : N/A		Post Load Test NDT done by : N/A			
Expiration of Load Test : N/A							
Result				PASS	☒	FAIL	
Is the above a defect which is of immediate danger to persons?				YES		NO	☒
Is the above a defect which is not yet but could become a danger to persons?				YES by :		NO	☒
Particulars of any repair, renewal or alteration required to remedy the defect identified above: N/A							
Is this equipment safe to operate?				YES	☒	NO	

Note: We thus attest that the aforementioned equipment has undergone a thorough Visual Inspection and /or Functional Test conducted by a qualified inspector in accordance with Engineering Corner for Inspection (E.C.I.) procedure / local / international standards.

Liability: The client or this assignee or supervisor in interest agrees to identify and hold harmless **Engineering corner for inspection Co.Ltd.** from and against any all claims, demands, lawsuits or actions for damages including legal fees to persons and/or property tangible, intangible or otherwise which may be against, **Engineering corner for inspection Co.Ltd.** incidental to arising out of or in connection with the work to be done, services to be performed or material to be furnished hereunder except for those claims caused solely and completely by the negligence of **Engineering corner for inspection Co.Ltd.** its directors, others, employees or sub-contractors.

Inspected by: ABDUL KHADER Signature:	Approved & Reviewed By: NAJUMUDEEN 	QA/QC DEPARTMENT #185 	QR Code:
--	--	---------------------------	--------------

	Engineering Corner for Inspection Company Limited INSPECTION CHECKLIST Forklift	Doc. No.	ECIR - LFT - 78
		Rev. No.	03
		Rev. Date	17-FEB-2026
		Page No.	2 of 4


Issue Number : 02 & Issue Date : 03-FEB-2020

Equipment Owner	SUDHIR EQUIPMENT RENTAL COMPANY /	Report No. & Date	134479 22-Jun-2026
Manufacturer / Year	TOYOTA / 2020	Location	SIEMENS WARE HOUSE, DAMMAM
Type / Model	HEAVY EQUIPMENT / FORKLIFT / 8FBJ35	Equipment ID. No.	SE3FLT-033
Inspection Date	22-Jun-2026	Equipment Sr. No.	8FBJ35-13005
Inspector Name	ABDUL KHADER	Capacity / SWL	3500 kg
Standard	ANSI/ITSDF B56.1-2020 & ITSDF B56.6-2021 & SASO-GSO-ISO-5057-1993	Expiration Date	21-Dec-2026

Item No	ITEM NAME	PASS	FAIL	N/A	Item No	ITEM NAME	PASS	FAIL	N/A
GENERAL REQUIREMENTS & DOCUMENTATION					4.3	Hydraulic System: Hoses, lines, and cylinders show no leaks, abrasion, or damage	☒		
1.1	Equipment documentation (manual, log) is available	☒			4.4	Forks: No cracks; heel wear ≤10%; no excessive horizontal/vertical bend	☒		
1.2	Previous inspection reports are checked and reviewed	☒			4.5	Fork Rating/Serial No.: Visible on fork heel	☒		
1.3	A durable, legible nameplate with Rated Capacity is installed	☒			4.6	Fork Positioner/Lock: Functional and secure	☒		
1.4	Load capacity chart is visible and legible to the operator	☒			4.7	Attachment(s): Properly marked, installed, and functioning correctly			☒
1.5	Operator is trained, certified, and authorized for the specific truck	☒			4.8	Attachment Locking Mechanism: Functional and secure			☒
1.6	Fire extinguisher is in place (min. 5BC for IC engines)	☒			OPERATOR COMPARTMENT & CONTROLS				
1.7	All warning labels and placards (e.g., seat belt, handholds) are present and legible	☒			5.1	Compartment: Clean, free of obstructions, leaks, and sharp edges	☒		
POWER SOURCE & SYSTEMS					5.2	Access: Steps and handholds are secure and in good condition	☒		
2.1	Electric Powered: Battery is secured, hold-downs in place, connectors insulated	☒			5.3	Seat Belt: Present and in good condition	☒		
2.2	IC Powered: No major fluid (oil, fuel, coolant) leaks; air filter clean			☒	5.4	Operator Restraint (e.g., Lap Bar): Functional (if equipped)	☒		
2.3	IC Powered: Exhaust system is intact, secure, and not leaking			☒	5.5	Lifting Enclosure (Rough Terrain): Locks securely in raised & lowered positions	☒		
2.4	LP Powered: Tank/Regulator secure, no leaks, hose in good condition			☒	5.6	Gauges and Indicators: All functional (hour meter, fuel, temp, warnings)	☒		
CHASSIS, FRAME & PROPULSION					5.7	Controls (Lift/Lower/Tilt/Attachment): Function correctly and return to neutral	☒		
3.1	Frame & Overhead Guard: No cracks, welds, or excessive corrosion	☒			5.8	Directional Control: Functions correctly (F/N/R)	☒		
3.2	Tires (Pneumatic): Serviceable, no excessive wear, cuts, or visible cords			☒	5.9	Horn/Audible Warning Device: Operational	☒		
3.3	Tires (Cushion): Serviceable, no excessive wear, or separation	☒			5.10	Foot Pedals: Anti-slip surface, free of grease/oil	☒		
3.4	Wheel and Axle Bolts/Nuts: Present and securely tightened	☒			OPERATIONAL CHECKS (With Engine/Power On)				
3.5	Steering System: Operates smoothly with no excessive play or binding	☒			6.1	Start-up: No unusual noises or warning indicators	☒		
3.6	Articulation Frame & Locking Pin (Rough Terrain): No excessive wear; pin engages correctly	☒			6.2	Travel Control (F/N/R): Smooth operation, no jerking; brakes effectively	☒		
3.7	Braking System (Service/Park): Holds on grade, no excessive pedal travel	☒			6.3	Steering & Articulation: Smooth operation, full left/right turn without binding	☒		
3.8	Travel & Reverse Alarm: Operational	☒			6.4	Parking Brake: Holds on rated incline	☒		
3.9	Lights (Head/Tail/Warning): Operational (if equipped)	☒			6.5	Hydraulic Lift/Lower & Tilt: Smooth operation, no creep or drift	☒		
MAST, FORKS & LOAD HANDLING					6.6	Attachment Function: Operates as designed (if equipped)			☒
4.1	Mast: No visible damage, distortion, or excessive wear on rollers/guides	☒			6.7	Safety Devices: Verify function of all interlocks and warning systems	☒		
4.2	Mast Chains & Cables: No kinks, corrosion, strand breaks, or improper tension	☒							

Inspected By : ABDUL KHADER	Customer Representative : arif
------------------------------------	---------------------------------------

Certificate Number: ECI/SA/C-03089/26





ECI. 110066

Capacity : 3500 kg

Equipment No. : SE3FLT-033

Serial No. : 8FBJ35-13005

Inspected Date : 22-Jun-2026

Next Inspection : 21-Dec-2026

Inspector : ABDUL KHADER

P.O.Box 235 Rastanura 31941 Kingdom of Saudi Arabia

Tel.: (013) 667-6999 / 667-6895 Fax #:(013) 667-6894

E-mail Address: eci@eccgroupksa.com



FORIC LIFT-F
ENGINEERING CORNER FOR
INSPECTION COMPANY LTD.



ECI.110066

Capacity : 3500 kg @ 500 mm

Equipment No. : SE3FLT-033

Serial No. : 8FB535-13005

Inspected Date : 22 JUN 2026

Next Inspection : 21 DEC 2026

Inspector : KHAOER ALLEY

P.O.Box 235 Rastanura 31941 Kingdom of Saudi Arabia
Tel.: (013) 667-6999 / 667-6895 Fax #:(013) 667-6894
E-mail Address: eci@eccgroupksa.com

